

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 27 Jan 2023

Preliminary Advice

Vehicle No	: SFJ7882B	Accident Date	: 14/01/2023
Make	: TOYOTA HARRIER	Policy No.	: DMPG22006195
Assignment Date	: 16/01/2023	Excess	: S\$0.00
Date of Inspection	: 16/01/2023	Est. Duration of Repair	: 10
Inspection At	: SPEEDWERKZ PTE LTD (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE SINGAPORE 147807		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	82,145.52
Revised Amount	:S\$	15,674.59
Check Items (Estimated)	:S\$	18,294.88
Total	:S\$	33,969.47

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	86,000.00
COE / PARF Rebate	:S\$	43,071.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,929.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.