

SPEEDWERKZ PRIVATE LIMITED

1 Kaki Bukit Avenue 6 #01-73, AUTOBAY, Singapore 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SFJ7882B

MAKE & MODEL: TOYOTA HARRIER

DOA: 14/1/2023

CLAIM TYPE: OD CLAIM

not Authorized
for
works
16/1/23
1/5 &
Whipple Attorneys
Excess?
10 days.

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BUMPER	1	\$1,018.13	✓
FRONT BUMPER AIR GRILLE	1	\$746.39	X
FRONT BUMPER REINFORCEMENT	1	\$443.45	X
FRONT BUMPER SIDE RETAINERS @115.20	2	\$195.84	12c 97.92 ✓
FRONT BUMPER FOG LAMP @516 RH	2	\$438.60	?
FRONT BUMPER CENTRE SPONGE	1	\$146.20	X
FRONT BUMPER TOW COVER @78.60	2	\$133.62	X
FRONT BUMPER PARKING SENSOR @481.90	2	\$819.23	X
FRONT BUMPER CENTER PARKING SENSOR HOLDER @78.00	2	\$132.60	X
FRONT BUMPER CORNER SPONGE @49.80	2	\$84.66	X
FRONT RADAR SENSOR	1	\$2,102.05	X
FRONT WIPER GRILLE	1	\$746.39	X
FRONT WIPER GRILLE CORNER GARNISH @47.60	2	\$80.92	X
FRONT BONNET	1	\$1,685.55	X
FRONT BONNET LOCK	1	\$139.91	X
FRONT BONNET INSULATOR	1	\$652.29	X
FRONT BONNET ABSORBER HOLDER @475	2	\$807.50	X
FRONT BONNET HINGES @87.10	2	\$148.07	X
FRONT GRILLE ASSY	1	\$1,148.69	X
FRONT BONNET CHROME MOULDING	1	\$395.76	X
FRONT SUPPORT PANEL	1	\$951.15	X
FRONT SUPPORT PANEL TOP GARNISH	1	\$340.17	X
FRONT HEADLAMP @6772.90 RH	1	\$5,756.97	?
FRONT FENDER @1448.30 RH	1	\$1,231.06	12c 615.53 ✓
FRONT FENDER INNER SHIELD @522 RH	1	\$443.70	12c 221.85 ✓
FRONT FENDER TOP SEAL @85.40 RH	1	\$72.59	X
FRONT FENDER TOP QUARTER GARNISH @75 RH	1	\$63.75	X
FRONT BUMPER CENTRE TOP BEAM	1	\$265.20	X
FRONT BUMPER SIDE TOP BEAM RH	1	\$90.10	X
RADIATOR ASSY	1	\$2,239.24	X
RADIATOR TOP HOSE	1	\$62.39	X
RADIATOR BOTTOM HOSE	1	\$77.27	X
RADIATOR FAN MOTOR	1	\$476.09	X
RADIATOR FAN COWLING	1	\$301.84	X
RADIATOR FAN BLADE	1	\$215.22	X
RADIATOR TOP PLATE	1	\$209.95	X
RADIATOR SIDE GARNISH @85	2	\$144.50	X
AIR CON CONDENSER	1	\$1,737.49	X
AIRCON FAN MOTOR	1	\$476.09	X
AIRCON FAN COWLING	1	\$301.84	X
AIRCON FAN BLADE	1	\$215.22	X
HORN @148	2	\$251.60	X
AIR CON CONDENSER SIDE GARNISH @85	2	\$144.50	X
RADIATOR SPARE TANK	1	\$424.75	?
WIPER WASHER TANK	1	\$129.88	?
WIPER WASHER TANK MOTOR @295.10	2	\$501.67	?
AIRCON LIQUID PIPE	1	\$404.69	X
AIRCON SUCTION HOSE	1	\$423.47	X
AIRCON DISCHARGE HOSE	1	\$626.71	X

AIRCON LIGHT PRESSUER HOSE	11	1	\$1,091.40	X
FRONT DOOR CHROME MOULDING	11	1	\$243.10	X
FRONT DOOR HINGES @75 RH	11	2	\$127.50	X
FRONT DOOR RH	R	1	\$1,633.96	X
FRONT DOOR GLASS REGULATOR MOTOR RH	11	1	\$735.00	X
FRONT DOOR RUBBER RH	11	1	\$312.21	X
FRONT DOOR LOWER GARNISH RH	11	1	\$329.80	X
FRONT WHEEL BEARING RH		1	\$667.25	?
FRONT LOWER ARM RH		1	\$622.20	?
FRONT SHOCK ABSORBER		1	\$545.87	?
REAR DOOR CHROME MOULDING	11	1	\$250.75	X
REAR DOOR LH	R	1	\$1,460.30	X
REAR FENDER ARCH GARNISH	11	1	\$350.80	X
ROCKER PENAL MOULDING	11	1	\$290.96	X
REAR SHOCK ABSORBER LH		1	\$460.02	?
REAR CONTROL ARM LH		1	\$354.62	?
REAR KNUCKLE ARM LH		1	\$607.92	?
REAR LOWER ARM LH		1	\$538.31	?
REAR HUB BEARING LH		1	\$294.95	?
REAR BOOT LID	no sent	1	\$2,175.32	/
REAR BOOT LID LOCK	11	1	\$590.92	X
REAR BOOT LID LOCK CATCH	11	1	\$166.60	X
REAR BOOT LID ABSORBER HOLDER (AUTO) 786.50	11	2	\$1,337.05	X
REAR BOOT LID HINGES @136.30	11	2	\$231.71	X
REAR BOOT RUBBER	11	1	\$288.66	X
REAR BOOT INSULATOR	11	1	\$474.98	X
REAR TURBO EMBLEM	11	1	\$64.01	X
REAR BOOT LID CENTRE GARNISH	11	1	\$501.08	X
REAR BOOT LID EMBLEM (HARRIER)	11	1	\$75.14	/
REAR BOOT LID REFLECTOR LAMP @499.60	11	2	\$764.32	X
REAR BOOT LID SIDE AUTO GATE SENSOR @422	11	2	\$717.40	X
REAR END PANEL	no sent	1	\$803.51	/
REAR END PANEL TOP GARNISH		1	\$304.73	?
REAR FLOOR PANEL		1	\$1,786.87	?
REAR TAIL LAMP @1233.80	N/S zero	2	\$2,097.46	12C
REAR FENDER INNER GARNISH @918.10	N/S zero	1	\$780.39	12C
REAR BUMPER	D. 11	1	\$1,237.77	/
REAR BUMPER SIDE RETAINER @121.90	one sent	2	\$207.23	/
REAR BUMPER REINFORCEMENT	N 2	2	\$701.42	?
REAR BUMPER SENSOR @225	M. 1	4	\$765.00	/
REAR BUMPER SENSOR HOLDER @25	M. 1	4	\$85.00	/
REAR BUMPER INNER SPONGE	M. 1	1	\$140.42	/
REAR BUMPER DIFFUSER	M. 1 NN	1	\$551.23	X
REAR BUMPER REFLECTOR @76.30	M. 1	2	\$129.71	/
REAR BUMPER LOWER COVER	air vent 1(1)	1	\$177.65	2
REAR EXHAUST SILENCER	11	1	\$846.86	Q
REAR EXHAUST RUBBER @45	11	2	\$76.50	Q
REAR EXHAUST CENTRE PIPE	11	1	\$860.37	Q
REAR FENDER @1875 RH	N/S 3 only 20	1	\$1,593.75	12C
REAR FLOOR PANEL TOP COVER		1	\$294.95	?
REAR FENDER INNER PANEL @1680		1	\$1,428.00	?

\$63,817.75

ADD 10 %

\$6,381.77

Sub Total

\$70,199.52

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR SPORT RIM 8 front sport rim	1	\$2,200.00	8025/N
REAR TYRE	1	\$850.00	?
REAR NUMBER PLATE	11	\$45.00	X
REAR BOOT INSULATOR CLIPS @7	11	\$45.00	X
REAR END PANEL TOP GARNISH CLIPS @7	11	\$56.00	X
REAR FENDER INNER GARNISH CLIPS @7	11	\$140.00	X
TAILGATE WINDSCREEN SEALANT	11	\$100.00	40

REAR END PANEL SEALANT	11	1	\$1,000.00	X
FRONT NUMBER PLATE	11	1	\$45.00	X
FRONT SUPPORT PANEL TOP GARNISH CLIPS	11	1 SET	\$45.00	X
Sub Total			\$4,526.00	

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING AND DIAGNOSTIC		\$550.00	30
REMOVE AND REPLACE WINDSCREEN	11	\$120.00	✓
REMOVE AND REFIX EXHAUST PIPE	11	\$160.00	X
REMOVE AND REFIX UPHOLTERY		\$160.00	60
REMOVE AND REPLACE REVERSE SENSOR		\$160.00	40
REMOVE AND REFIX RADIATOR	11	\$120.00	X
REMOVE AND REFIX AIRCON CONDENSER & REFILL GAS	11	\$150.00	X
LABOUR CHARGE FOR KNOCK DENT AND RENEW PARTS		\$3,500.00	1800
TO SPRAY PAINTING		\$2,500.00	1800
Sub Total			\$7,420.00

Grand Total \$82,145.52