



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|---|-----------------|----------------------|
| MASSIVE TRADING & AUTO | | | Ref: | CS/TP23000503/Kwy3e2 |
| BLK 203 HOUGANG ST 21 #04-91 SINGAPORE 530203 | | | Date: | 17/01/2023 |
| ON BEHALF OF TAN KIAN BOON | | | Code: | TP342 |
| 1. Policy Particulars :- THIRD PARTY (FOLLOW THROUGH INSPECTION) | | | | |
| | Insured Veh. | Veh. Inspected | SLZ 1913E | |
| | Policy No. | Coverage (\$) | 0.00 | |
| | Claim No. | Excess (\$) | 0.00 | |
| | Assign From | Assign Date | 04/01/2023 | |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | TOYOTA C-HR (A) | c.c | 1797 |
| | Engine No. | HIDDEN | Year of Reg. | 2018 |
| | Chassis No. | ZYX102099224 | Colour | METALLIC BROWN |
| | Odometer | 348439 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 225/50 R18 | BRIDGESTONE | 3 mm |
| | L/H Front Tyre | 225/50 R18 | BRIDGESTONE | 3 mm |
| | R/H Rear Tyre | 225/50 R18 | YOKOHAMA | 7 mm |
| | L/H Rear Tyre | 225/50 R18 | YOKOHAMA | 7 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. | | | |
| | DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 01/01/2023 | Inspection Date | 04/01/2023 |
| | Survey held at | MASSIVE TRADING & AUTO BLK 203 HOUGANG ST 21 #04-91 SINGAPORE 530203 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 8 Working Days | |