



Section A - Accident Details

Registration Number	SHB5360Y
Case Reference Number	TAX/01/23/2007
Registration Date	19/Dec/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	MAHMUD BIN MOBATTULLAH
Type of Accident	Head to Rear
Accident Date and Time	5/Jan/2023 3:15 PM
Accident Reported Date and Time	6/Jan/2023 8:58 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117322
Special Instruction to ARC, if any	TP/ RIGHT REAR PORTION
Prepared Date and Time	6/Jan/2023 9:47 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$700.00
Total Spray Cost	\$1,296.00	\$550.00
Total Spare Part Cost	\$6,200.92	\$1,787.65
Total Other Cost	\$820.00	\$110.00
TOTAL COST	\$9,668.92	\$3,147.65
Lump Sum Total	\$9,650.00	\$3,150.00 (L/S)
Number of Repair Days	8.0	6.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / Allianz Insurance
ARC / Surveyor Sign Off Date	13/01/2023 5:21 PM	13/01/2023 3:25 PM
Signature		
Remarks	LUMPSUM REPAIR / AFTER REPAIR PHOTOS, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR HP 9749 5749	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2302-0143	Invoice Number	
Quotation Date	15.02.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$1,352.00	\$700.00
Total Labour	\$1,352.00	\$700.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY DOOR HANDLE	\$180.00	\$50.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,296.00	\$550.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$80.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$820.00	\$110.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace	Replace
		6787147051	WEATHERSTRIP, REAR DOOR RH	0.00	\$194.60	0.00	\$0.00	Replace	Not Given
		6863047050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given
		6980347020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	0.00	\$223.50	0.00	\$0.00	Replace	Not Given
		8572047150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given
		6877052031	HINGE ASSY, REAR DOOR, LOWER RH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given
		6875020122	HINGE ASSY, REAR DOOR, UPPER RH	0.00	\$107.00	0.00	\$0.00	Replace	Not Given
		7585047910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	100.00	\$0.00	Replace	Repair
		4877047010	ARM ASSY, UPPER CONTROL, REAR RH	0.00	\$455.00	0.00	\$0.00	Replace	Check

√
X
X
X
X
X
X
X
R
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/02/2023

User ID : PohSuan

		43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$722.10	0.00	\$0.00	Replace	Check	X
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
		42611474 50	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace	Replace	√
		65637470 60	LINER, REAR FENDER , RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	X
		42450760 20	HUB & BEARING ASSY WITH SPEED SENSOR , REAR	0.00	\$644.10	0.00	\$0.00	Replace	Check	X
		48530807 91	ABSORBER SET, SHOCK, REAR RH & LH	0.00	\$137.50	0.00	\$0.00	Replace	Check	X
		69211470 21A1	DOOR OUTER HANDLE REAR, RH	1.00	\$105.50	100.00	\$0.00	Replace	Repair	R
		69050522 50	DOOR LOCK REAR , RH	0.00	\$607.90	0.00	\$0.00	Replace	Not Given	X
		67003-47211	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,401.70	100.00	\$0.00	Replace	Repair	R
		65565470 10	PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$37.70	0.00	\$0.00	Replace	Check	X
		67836330 30	DOOR REAR LOCK COVER	0.00	\$10.00	0.00	\$0.00	Replace	Not Given	X
Total					\$9,842.84		\$2,234.56			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	2,234.56	
	-20%	
	1787.65	L/S \$3,150/-
+	700.00	
+	660.00	
	3,147.65	