

1/13/23, 3:36 PM

https://vacswb.smrt.com.sg/Estimation.aspx

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation		Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
				Part Name											
Standard	Main			NUMBER PLATE		1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	bt-
Standard	Main			NUMBER PLATE FRAME		1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace	de-
Standard	Main			FASCIA-RR BPR		1	758.48	758.48	10.00	682.63	Replace	1	682.63	Replace	de-
Standard	Main			FASCIA-RR BPR LWR		1	230.68	230.68	10.00	207.61	Replace	1	207.61	Replace	de-
Standard	Main			FINISHER-RR BPR - RH		1	47.42	47.42	10.00	42.68	Replace	1	0	Repair	Xm
Standard	Main			FINISHER-RR BPR - LH		1	47.42	47.42	10.00	42.68	Replace	1	0	Repair	avg
Standard	Main			BRACKET ASM-RR BPR FASCIA SI-RH		1	29.85	29.85	10.00	26.87	Replace	0	0	Check	X
Standard	Main			BRACKET ASM-RR BPR FASCIA SI-L		1	29.85	26.87	10.00	26.87	Replace	0	0	Check	X
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - RH		1	46.08	46.08	10.00	41.47	Replace	0	0	Check	X
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - LH		1	46.08	46.08	10.00	41.47	Replace	0	0	Check	X
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - RH		1	12.80	12.80	10.00	11.52	Replace	0	0	Check	X
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - LH		1	12.80	12.80	10.00	11.52	Replace	0	0	Check	X
Standard	Main			BAR ASM-RR BPR IMP		1	339.77	339.77	10.00	305.79	Replace	0	0	Check	X
Standard	Main			LAMP ASM-TAIL(BODY SI) - LH		1	764.09	764.09	10.00	687.68	Replace	0	0	Check	X
Standard	Main			LAMP ASM-TAIL(BODY SI) - RH		1	764.09	764.09	10.00	687.68	Replace	0	0	Check	X
Standard	Main			LAMP ASM-TAIL(LID SI) - LH		1	407.68	407.68	10.00	366.91	Replace	0	0	Check	X
Standard	Main			LAMP ASM-TAIL(LID SI) - RH		1	407.68	407.68	10.00	366.91	Replace	0	0	Check	X
Standard	Main			LAMP ASM-RR FOG - RH		1	189.07	189.07	10.00	170.16	Replace	0	0	Check	X
Standard	Main			LAMP ASM-RR FOG - LH		1	36.30	36.30	10.00	32.67	Replace	0	0	Check	X
Standard	Main			SENSOR-RR PARK DIST CONT		3	65.00	195.00	10.00	175.50	Replace	0	0	Check	X
One Time Key In	Main			CAP-R/WDO WPR ARM FIN		1	6.14	6.14	10.00	5.53	Replace	1	5.53	Replace	mis-

Total Spare Part Cost 7,295.38

Surveyor Total 2,872.00

Lump Sum Discount (%) 0.00

Lump Sum Dis (%)

Final Spare Part Cost 7,295.38

Final Sur Total 2,872.00

Labour's Cost Detail

3089.64
10% - 278.68 } 2914.68
SW 134

https://vacswb.smrt.com.sg/Estimation.aspx

REC BY:

A.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,200.00	800	
Total:			1,200.00	800.00 ✓	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	428.00	220	
2	Main	TO RESPRAY REAR PANEL	230.00	0 <i>Kun</i>	
3	Main	TO RESPRAY TAIL GATE	428.00	220	
Total:			1,086.00	440.00 ✓	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 <i>Kun</i>	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 <i>Kun</i>	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
4	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	60	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	350.00	0 <i>Kun</i>	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
7	Main	TO REMOVE AND REFIX REAR WINDSCREEN	120.00	120.00	
8	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>Kun</i>	
9	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	
10	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
Total:			1,590.00	540.00 ✓	

Summary

	Estimator Assessment(\$)
Total Spare Part Detail	7,295.38
Total Labour Cost	1,200.00

Surveyor Assessment(\$)
2,872.00
800.00

2914.68
 800
 440
 540
 44694.68, 5 days
 #

1/13/23, 3:36 PM

<https://vacsweb.smr.com.sg/Estimation.aspx>

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spray Painting	1,086.00	440.00
Other	1,590.00	540.00
Overall Total	11,171.38	4,652.00
Lump Sum Repair Option		☐
Lump Sum Total	0.00	4,652.00
Surveyor Approved Amount		4,652.00
No of Repair Days*	8	5
Remarks		part by part repair / before PAINT PHOTO / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR HP 9749 5749 taufikh@lkkauto.com
Surveyor Name		Taufikh
Signature		
Survey Date	13/01/2023	Save Clear

Taufikh 97495749
WP- 13/1/23
r/p Resay before paint.
5 days
taufikh@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: