



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--------------------------------------|--|--------------------|
| MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581 | | Ref: CS/FCI23000511/Kvy3e2 Date: 05/04/2023 Code: FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | GBK 9902G | Veh. Inspected | SBL 9090T |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | D23000219MFCV | Excess (\$) | 0.00 |
| Assign From | HARMINDER KAUR | Assign Date | 16/01/2023 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA ALPHARD (A) | c.c | 2493 |
| Engine No. | HIDDEN | Year of Reg. | 2019 |
| Chassis No. | AGH300240819 | Colour | METALLIC BLACK |
| Odometer | 43277 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 235/50 R18 | MICHELIN | 9 mm |
| L/H Front Tyre | 235/50 R18 | MICHELIN | 9 mm |
| R/H Rear Tyre | 235/50 R18 | MICHELIN | 9 mm |
| L/H Rear Tyre | 235/50 R18 | MICHELIN | 9 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 13/01/2023 | Inspection Date | 17/01/2023 |
| Survey held at | 160 Sin Ming Drive (Autocity) #06-03 | | |
| Repairer | KBS MOTORSPORTS PTE LTD | | |
| 5a. Remarks | | | |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 6 Working Days | |