

Your Ref : SNM23D200195/C01/TANCHC

Date: 19th Jan 2023

Our Ref : CS/CTI23000515/Kvp3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGS 3739A
ACCIDENT ON 07/01/2023**

Instruction was received to inspect the vehicle Reg. No. SGS 3739A. The inspection was conducted on 16/01/2023 at the premises of M/s S & H Motor Pte Ltd, 160 Sin Ming Drive #07-02 Sin Ming Autocity, Singapore 575722.

The following vehicle information was recorded:

Registration Number	: SGS 3739A
Make/Model	: Volkswagen Golf 1.4 TSI AT 5G13HZ HID SR
Year of Registration	: 2016
Body Colour	: Metallic Blue
Chassis Number	: WVWZZZAUZHW073457
Engine Capacity	: 1395 cc
Speedometer Reading	: 53492 km

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is S\$35,000.00 (Sin Dollars: Thirty-Five Thousand only.) (Details see photographs enclosed)

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 56,000.00(est)

Less: LTA Reimbursement Value (RV)

(S\$ 30,171.00)

S\$ 25,829.00

Less: Excess

(S\$ 500.00)

Nett Liability

S\$ 25,329.00

(b) If the vehicle to be "Repair"

Repair Cost

S\$ 35,000.00

Less: Excess

(S\$ 500.00)

Nett Liability

S\$ 34,500.00

(a) – (b) =

(S\$ 9,171.00)

=====

The amount of estimated saving of S\$9,171.00 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.