

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23000532/SWY3Q2**Date:** 01/02/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ003084		
Claimant Vehicle No :	SHA1514C	Insured Vehicle No :	SMK87M		
Date of Loss:	15/01/2023	Nature of Claim:	TP	Claim No:	M2300312

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1514C		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4DFDU606743
Reg. Date:	19/05/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU089704
Colour:	Blue	Odometer:	712865 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,223.72	3,592.68	2,631.04	42.27
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,820.00	1,380.00	440.00	24.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,054.72	4,983.68	3,071.04	38.13
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	8,054.72	4,000.00	4,054.72	50.34
+ GST 8.00/8.00% (\$\$)	644.38	320.00	324.38	50.34
Nett Amount (\$\$)	8,699.10	4,320.00	4,379.10	50.34

INSPECTION

Date of Assignment:	16/01/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	17/01/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1514C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,052.20 FL	*- FL
2	1		*FRONT BUMPER BRACKET LH	Cracked	49.20 FL	*49.20 FL
3	1		*FRONT BUMPER GRIILE LH	Not Necessary	187.20 FL	*- FL
4	1		*FRONT FENDER LH	Buckled	663.00 FL	*663.00 FL
5	1		*FRONT FENDER SHIELD LH	Not Necessary	174.90 FL	*- FL
6	1		*FRONT WING MIRROR ASSY LH	Cracked	760.00 FL	*760.00 FL
7	1		*FRONT DOOR PANEL LH	Buckled	2,707.70 FL	*2,707.70 FL
8	1		*FRONT WHEEL COVER LH	Cut	217.20 FL	*217.20 FL
9	1		*FRONT WHEEL KNUCKLE LH	Not Necessary	552.00 FL	*- FL
10	1		*FRONT WHEEL HUB W/ BEARING LH	Not Necessary	673.20 FL	*- FL
11	1		*FRONT STRG TIE ROD LH	Not Necessary	125.20 FL	*- FL
12	1		*FRONT STRG BALL JOINT LH	Not Necessary	73.10 FL	*- FL
13	1		*FRONT SHOCK ABSORBER LH	Not Necessary	342.20 FL	*- FL
14	1		*FRONT SHOCK ABSORBER MTG LH	Not Necessary	108.80 FL	*- FL
15	1		*FRONT DOOR COMFORT STICKER	Necessary	75.00 FS	*75.00 FS
					Sub Total (\$\$)	7,760.90 4,472.10
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,537.18 879.42
					Total Parts (\$\$)	6,223.72 3,592.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	600.00
2	SPRAY PAINTING	New	800.00	750.00
3	REMOVE/REFIX FRONT UC SUSPENSION.	New	120.00	0.00
4	CHECK LIGHTING & WIRING	New	60.00	30.00
5	RESET FRONT WHEEL ALIGNMENT	New	90.00	0.00
Gross Labour Cost (\$\$)			1,820.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >