

ASS. REC. BY:

REF:

AIS/23000533/K943

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1. B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNE 89065

Yr Regn:

04, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mr CLA 180

c.c

1332

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

12373

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WIK1183842N 298429

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

7

mm

L/Bal.

3

mm

L/Bal.

7

mm

D.O.A.

5/1/23

D.O.I.

17/1/2023

Survey held at

Des. of Damages: (Frt) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/3 @ 5618.50 Carlin (Red #1841.55, 25%)

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

MEK-00

Lump Sum / I.B.I. (\$

5618.50



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT

TEL :

FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 05/01/2023

ESTIMATE

NO : QUOT202301-000044(00)

DATE : 16/01/2023

POLICY NO : SP2003907937

VEH REG NO : SNE8906S

MAKE/MODEL : MERCEDES BENZ CLA180
COUPE PROGRESSIVE

CHASSIS NO : W1K1183842N296429

ENGINE NO : 28291480793059

REG. DATE : 2022

Not Whairu
Rehmy Bepain
3 days
85618.50

Estimate Repair Cost to Vehicle No : SNE8906S

Description	Quantity	Unit Price	Amount	
		S\$	S\$	
PARTS				
1 Headlamp assy - LH	1	1,880.00	1,880.00	
2 Front grille	1	195.00	195.00	
3 Front grille logo	1	138.00	138.00	
4 Front grille beam	1	145.00	145.00	
5 Front grille inner support	1	68.00	68.00	
6 Front grille air duct	1	115.00	115.00	
7 Front bumper	1	980.00	980.00	
8 Front bumper reinforcement	1	325.00	325.00	
9 Front bumper sponge	1	105.00	105.00	
10 Front bumper top garnish	1	128.00	128.00	
11 Front bumper lower chrome	1	168.00	168.00	
12 Front bumper sensor seals	6	8.00	48.00	
13 Front bumper clips	15	5.50	82.50	
			4,377.50	
			Add 10%	437.75
			4,815.25	
SPECIAL NET				
14 Front number plate	1	40.00	40.00	
			40.00	
LABOUR				
15 To remove and refit front bumper sensor	1	100.00	100.00	
16 To check and rectify wiring system	1	80.00	80.00	
17 To panel beat and straighten support panel, front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00	
18 To putty and spray paint on accident areas	1	1,000.00	1,000.00	
19 To reset and reprogram headlamp fault code	1	350.00	350.00	
			2,530.00	
TOTAL			S\$ 7,385.25	
ADD GST @ 8%			590.82	
GRAND TOTAL			S\$ 7,976.07	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Front number plate garnish not 868 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Front number plate garnish
nd 868

SINGAPORE DOLLAR SEVEN THOUSAND NINE HUNDRED SEVENTY-SIX AND CENTS SEVEN ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 05/01/2023

ESTIMATE

NO : QUOT202301-000044(00)

DATE : 16/01/2023

POLICY NO : SP2003907937

VEH REG NO : SNE8906S

MAKE/MODEL : MERCEDES BENZ CLA180
COUPE PROGRESSIVE

CHASSIS NO : W1K1183842N296429

ENGINE NO : 28291480793059

REG. DATE : 2022

Estimate Repair Cost to Vehicle No : SNE8906S

Description	Quantity	Unit Price	Amount
		S\$	S\$

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE