



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT

TEL :

FAX : 17/1/23 3days

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 05/01/2023

ESTIMATE

NO : QUOT202301-000044(00)
DATE : 16/01/2023
POLICY NO : SP2003907937
VEH REG NO : SNE8906S
MAKE/MODEL : MERCEDES BENZ CLA180
COUPE PROGRESSIVE
CHASSIS NO : W1K1183842N296429
ENGINE NO : 28291480793059
REG. DATE : 2022

Estimate Repair Cost to Vehicle No : SNE8906S

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy - LH	1	1,880.00	1,880.00 2 ✓
2 Front grille	1	195.00	195.00 2 ✓
3 Front grille logo	1	138.00	138.00 ✓
4 Front grille beam	1	145.00	145.00 ✓
5 Front grille inner support	1	68.00	68.00 7 ✓
6 Front grille air duct	1	115.00	115.00 7 ✓
7 Front bumper	1	980.00	980.00 ✓
8 Front bumper reinforcement	1	325.00	325.00 7 ✓
9 Front bumper sponge	1	105.00	105.00 7 ✓
10 Front bumper top garnish	1	128.00	128.00 X
11 Front bumper lower chrome	1	168.00	168.00 ✓
12 Front bumper sensor seals	6	8.00	48.00 ✓
13 Front bumper clips	15	5.50	82.50 ✓
Front number plate garnish 868			4,377.50
Add 10%			437.75
			4,815.25
SPECIAL NET			
14 Front number plate	1	40.00	40.00 805N
LABOUR			
15 To remove and refit front bumper sensor	1	100.00	100.00 601
16 To check and rectify wiring system	1	80.00	80.00 201
17 To panel beat and straighten support panel, front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 301
18 To putty and spray paint on accident areas	1	1,000.00	1,000.00 2501
19 To reset and reprogram headlamp fault code	1	350.00	350.00 7
			2,530.00 880
TOTAL			S\$ 7,385.25
ADD GST @ 8%			590.82
GRAND TOTAL			S\$ 7,976.07

SINGAPORE DOLLAR SEVEN THOUSAND NINE HUNDRED SEVENTY-SIX AND CENTS SEVEN ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 05/01/2023

ESTIMATE

NO : QUOT202301-000044(00)

DATE : 16/01/2023

POLICY NO : SP2003907937

VEH REG NO : SNE8906S

MAKE/MODEL : MERCEDES BENZ CLA180
COUPE PROGRESSIVE

CHASSIS NO : W1K1183842N296429

ENGINE NO : 28291480793059

REG. DATE : 2022

Estimate Repair Cost to Vehicle No : SNE8906S

Description	Quantity	Unit Price	Amount
		S\$	S\$

parts: \$ 4,658.50
SN: 80.00
Labour: 880.00

\$ 5,618.50
XS 700.00

\$ 4,918.50
8% 393.48

\$ 5,311.98

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE