



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

Finalization

## ESTIMATE FOR SMH2716J

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT  
6 RAFFLES QUAY  
#21-00  
SINGAPORE 048580  
65073848

## Vehicle &amp; Document Information

WIP No **62422**  
Reg No/Reg Date **SMH2716J / 21/01/2019**  
Date In/Mileage **13/02/2023/ 71258**  
Chassis No **WDD1770872J0481012**  
Engine No **28291480034740**  
Make/Model **MB/MB A 200 Progressive**  
Colour/Trim **027 775 Iridium sil/ 041 111 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	13/03/2023/ 21:09	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : GA434029/01 // 14-1-2023 DRIVE IN/TP VEH NUMBER : 16-1-2023 // XE3356T - FIRST CAPITAL DATE IN/DATE SURVEY: 13-2-2023 // RASUL - L.K.K DIRECT SETTLEMENT BY: 1-2-2023 // VIC SANGHILAN - FIRST CAPITAL				1440.00
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.			0.05	1600.00
A BPIRES RESpray REAR BUMPER & TAILGATE			0.10	380.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				120.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				
X REAR BUMPER	1.00	1353.60	00.00	1353.60
X REAR BUMPER LOWER BLACK TRIM	1.00	281.47	00.00	281.47
X REAR BUMPER TRIM STRIP	1.00	183.46	00.00	183.46
X GROMMET	3.00	2.73	00.00	8.19
X MERCEDES STAR	1.00	52.05	00.00	52.05
X A-200 MODEL PLATE	1.00	129.43	00.00	129.43

Confirmed &amp; accepted by

8% GST on **Nett 5,548.20**  
**443.86**

Authorized signatory and company stamp

**Total Payable 5,992.06**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG