

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0040/2023/EQ
DATE : 12-Jan-23
WIP : 58551

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TEO CHER GUAN
ADDRESS : BLK 135 SERANGOON AVENUE 3
#05-04
SINGAPORE 556114
TELEPHONE : HP +65 96608990
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SNF 1053 T**
MODEL CODE : AUDI A3 SPORTBACK 1,5 TFS
MODEL YEAR : 29/4/2022
ENGINE NO : DFY 309731
CHASSIS NO : WAUZZZGY3NA026166
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Jan-23
PLACE OF ACCIDENT : JUNCTION OF ANG MO KIO AVENUE 6

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 1053 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	360.00	X.
2	TO RENEW RHS REAR 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N \$	300.00	✓
3	TO INSTALL SOLAR FILM FOR ALL THE AFFECTED GLASSES.	S/N \$	400.00	✓
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERYMANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	✓
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	✓
6	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	280.
TOTAL LABOUR CHARGES		:	\$ 4,560.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 1053 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW RHS REAR DOOR AND RHS FRONT DOOR. TO CUT OUT AND WELD RHS REAR FENDER AND RHS C-PILLAR INNER PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,700.00	4000.
8	TO RESPRAY RHS REAR FENDER, RHS SILL PANEL, RHS REAR DOOR, DOOR HINGES, RHS FRONT DOOR, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	\$ 6,000.00	5.5 x 550 = 3025 Handle x 2 = 200. <u>3225.</u>
9	TO RENEW RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	280.
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 18,972.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 1053 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR SIDE PANEL FRAME - RH <i>Distorted.</i>	1	\$ 3,561.00	✓
2	REAR QUARTER WINDOW - RH <i>New</i>	1	\$ 653.00	✓
3	WINDOW PRIMER <i>New</i>	1	\$ 24.00	✓
4	REAR FUEL FILLER FLAP <i>New</i>	1	\$ 102.00	+
5	REAR WHEEL HOUSING LINER - RH <i>?</i>	1	\$ 281.00	?
6	REAR WHEEL SPOILER - RH <i>New</i>	1	\$ 34.00	+
7	REAR DOOR - RH <i>Distorted</i>	1	\$ 3,148.00	—
8	REAR DOOR OUTER SEAL - RH <i>New</i>	1	\$ 189.00	✓
9	REAR DOOR ATTACHMENT PARTS <i>New</i>	1	\$ 283.00	+
10	REAR DOOR CATCH <i>?</i>	1	\$ 99.00	?
11	REAR DOOR HINGE HALF UPPER PART - RH UPPER <i>New</i>	1	\$ 51.00	+
12	REAR DOOR HINGE HALVES - RH UPPER <i>New</i>	1	\$ 51.00	+
13	REAR DOOR HINGE HALF UPPER PART - RH LOWER <i>New</i>	1	\$ 54.00	+
14	REAR DOOR HINGE HALF LOWER PART - RH LOWER <i>New</i>	1	\$ 57.00	+
15	REAR DOOR INNER SEAL <i>New</i>	1	\$ 189.00	+
16	REAR DOOR HANDLE TRIM PLATE - RH <i>Regis</i>	1	\$ 246.00	+
17	REAR DOOR HOUSING - RH <i>Regis</i>	1	\$ 59.00	+
18	REAR DOOR OUTER HANDLE WITH SENSOR - RH <i>New</i>	1	\$ 187.00	+
19	REAR DOOR UNDERLAY - RH FRONT <i>New</i>	1	\$ 7.00	+
20	REAR DOOR UNDERLAY - RH REAR <i>New</i>	1	\$ 8.00	+
SUB TOTAL SPARE PARTS			\$ 9,283.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 1053 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR HANDLE BASE <i>XTC u</i>	1	\$ 183.00	+
22	REAR DOOR BOWDEN CABLE	1	\$ 96.00	+
23	REAR WINDOW REGULATOR - RH ?	1	\$ 266.00	?
24	REAR WINDOW REGULATOR MOTOR - RH ?	1	\$ 332.00	?
25	REAR DOOR CONTROL UNIT <i>XTC u</i>	1	\$ 548.00	+
26	REAR WINDOW GUIDE - RH <i>XTC u</i>	1	\$ 314.00	+
27	REAR WINDOW GUIDE TRIM STRIP - RH <i>Not u</i>	1	\$ 186.00	+
28	REAR WINDOW SLOT SEAL TRIM STRIP - RH OUTER <i>XTC u</i>	1	\$ 333.00	+
29	REAR QUARTER WINDOW GUIDE RAIL - RH <i>XTC u</i>	1	\$ 55.00	+
30	REAR PILLAR C TRIM <i>Not u</i>	1	\$ 168.00	-
31	REAR PILLAR B TRIM - RH <i>Not u</i>	1	\$ 139.00	-
32	REAR WINDOW APERTURE SEAL - RH INNER ?	1	\$ 106.00	?
33	REAR DOOR TRIM - RH <i>XTC u</i>	1	\$ 2,207.00	+
34	REAR DOOR WIRING SET <i>Not u</i>	1	\$ 220.00	+
35	REAR DOOR TRIM PANEL WIRING HARNESS <i>Not u</i>	1	\$ 103.00	+
36	FRONT DOOR - RH <i>Repair</i>	1	\$ 3,269.00	+
37	FRONT DOOR OUTER SEAL - RH <i>XTC u</i>	1	\$ 189.00	+
38	FRONT DOOR CATCH <i>Not u</i>	1	\$ 99.00	+
39	FRONT TYRE PRESSURE DATA PLATE <i>Not u</i>	1	\$ 45.00	+
40	FRONT DOOR HANDLE TRIM PLATE - RH <i>Repair</i>	1	\$ 246.00	+
SUB TOTAL SPARE PARTS			\$ 9,104.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 1053 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT DOOR HANDLE CAP - RH <i>Not in</i>	1	\$ 39.00	+
42	FRONT SIDE PANEL INNER - RH LOWER ?	1	\$ 92.00	?
43	FRONT ALUMINIUM RIM <i>Not</i>	1	\$ 1,519.00	✓
44	FRONT ALUMINIUM RIM RUBBER VALVE <i>Not in</i>	1	\$ 4.00	+
45	ACRYLIC SEALANT	S/N	\$ 180.00	✓
46	CAVITY WAX	S/N	\$ 140.00	✓
47	STONE CHIP	S/N	\$ 180.00	✓
48	METAL FILLER POWDER	S/N	\$ 280.00	✓
49	1/4 GLASS SEALANT	S/N	\$ 100.00	✓
50	SUNDRIES ?		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 21,421.00	
TOTAL LABOUR CHARGES		:	\$ 18,972.00	
GRAND TOTAL		:	\$ 40,393.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Ling
13/01/23

Not Authorised, 15 Days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT