

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0038/2023/EQ
DATE : 12-Jan-23
WIP : 58714

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR K S KUMAR
ADDRESS : BLK 621 WOODLANDS DRIVE 52
#07-46
SINGAPORE 730621
TELEPHONE : HP +65 97432396
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210035229
VEHICLE NO : **SMZ 1520 T**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 13/4/2021
ENGINE NO : CZD C36195
CHASSIS NO : WAUZZZF33M1097033
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jan-23
PLACE OF ACCIDENT : NEAR TO TAMPINES COURTS

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 1520 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>4,272.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 1520 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deform d</i>	1	\$ 1,137.00	✓
2	FRONT BUMPER CLOSING ELEMENT - RH <i>not m</i>	1	\$ 70.00	x
3	FRONT BUMPER GRILLE - RH <i>not m</i>	1	\$ 131.00	+
4	FRONT BUMPER CLOSING ELEMENT <i>not m</i>	1	\$ 224.00	+
5	FRONT BUMPER SPOILER <i>lt</i>	1	\$ 451.00	-
6	FRONT BUMPER AIR GUIDE GRILLE - RH <i>not m</i>	1	\$ 181.00	x
7	HEADLIGHT MOUNTING - RH <i>not m</i>	1	\$ 140.00	+
8	HEADLIGHT - RH <i>lt</i>	1	\$ 6,305.00	✓
9	LIFT CYLINDER - RH <i>not m</i>	1	\$ 244.00	+
10	LIFT CYLINDER HOSE <i>not m</i>	1	\$ 96.00	x
11	FRONT WHEEL HOUSING LINER - RH <i>not m</i>	1	\$ 281.00	+
12	FRONT WHEEL HOUSING LINER COVER - RH <i>not m</i>	1	\$ 19.00	x
13	FRONT WHEEL COVER - LH / RH <i>lt Nec, RH ut</i>	2	\$ 598.00	-
14	SUNDRIES <i>?</i>		\$ 400.00	?
TOTAL SPARE PARTS			\$ 10,277.00	
TOTAL LABOUR CHARGES			\$ 4,272.00	
GRAND TOTAL			\$ 14,549.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *13/01/23.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: