



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	OD/012023/5921
Policy No:	SP2002799658-01	Date of Loss:	12/01/2023
Vehicle Reg. No.:	SNC3502S	Driveable?	
Driver Age/Info:	35 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG WEI REN, DARYL	Contact No:	+6594234204
Driver:	NG WEI REN, DARYL		
Make/Model:	MAZDA CX-5, 2.0 ELEGANCE 2WD I4 (A)	Vehicle Reg. Date:	14/10/2021
Vehicle Colour:	White	Chassis No:	JM6KF2W7AN0696130
Engine No:	PE31709764		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	SAME AS SKETCH		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	3,580.00
Miscellaneous Items	0.00
Labour	960.00
Paintwork Labour	680.00
Towing	0.00
Gross Total (S\$)	5,220.00
+ GST 8.00% (S\$)	417.60
Nett Amount (S\$)	5,637.60

This claim is handled by: MUHAMMAD ISWAN BIN ISHAK

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Reference

Version: 1.0 (Last Synchronised: 17 Jan 2023)

MAZDA CX-5 2.0 ELEGANCE 2WD I4 (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List)

Print Code: Vin's Motor Pte Ltd/SNC3502S/17/01/2023 14:05

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT GRILLE ASSY (order) broken	0.00	0.00	*970.00 F
2	1		*FRONT GRILLE EMBLEM (order) broken	0.00	0.00	*80.00 F
3	1		*NOSE PANEL (order) chipped	0.00	0.00	*260.00 F
4	5		*NOSE PANEL RIVET H/c	0.00	0.00	*20.00 F
5	1		*FRONT BUMPER (order) broken	0.00	0.00	*950.00 F
6	1		*FRONT BUMPER REINFORCEMENT (order) H/c	0.00	0.00	*480.00 F
7	10		*FRONT BUMPER CLIPS H/c H/c	0.00	0.00	*20.00 F
8	1		*FRONT SUPPORT PANEL H/c	0.00	0.00	*330.00 F
9	1		*FRONT SUPPORT TOP PANEL H/c	0.00	0.00	*90.00 F
10	1		*FRONT NO.PLATE H/c	0	0.00	*60.00 F

F=Franchise part, S=SpcNett.

Sub Total (S\$)	3,260.00
------------------------	-----------------

+ Margin on L,N Items 10.00% (S\$)	320.00
------------------------------------	--------

Total Parts (S\$)	3,580.00
--------------------------	-----------------

Vin's Motor Pte Ltd/SNC3502S/17/01/2023 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO SPRAY PAINTING	New	680.00 400/-
<u>Labour Items</u>			
2	TO RESET HEADLAMP SYSTEM	New	280.00 171
3	TO REPAIR DAMAGES	New	680.00 400/-
Gross Labour Cost (S\$)			1,640.00

Vin's Motor Pte Ltd/SNC3502S/17/01/2023 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

18/01/2023 @

N/A Andrew

P/Pat.

Photo after repair with damaged parts.

Tryn

2kk Auto

3 days.

2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: