

ASS. REC. BY:

REF:

ASNY 23000559/KV

C

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SHC 994X

Policy No. \_\_\_\_\_

Claims No. S3MO411B

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

10.30am

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 62k

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLP5059Y

Yr Regn: 06, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz

c.c.

1498

Colour: M. D. Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 53352

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMGK585014X201674

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 14/1/23

D.O.I. 19/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Est not ready

1/2 11pm @ 2900 Cash (red 5941.70, 67%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2) 7/2/23-typist

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees:

Others:

Report Format: TP

Lump Sum / L.B. (\$ 2900)

TOTAL

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	16/01/2023 11:09 (SGT)
Reported by	Both
Date of Accident	14/01/2023 11:55 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Along CTE towards SLE/TPE at Lamppost #19F
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP5059Y
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Loh Tick Kwang
NRIC No	S7320285Z
Email Address	loh_tick_kwang@hotmail.com
Mobile Phone No	(Phone) +65-84991358
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Jazz
Variant	JAZZ 1.5
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only
Vehicle Category	Private car
Transmission	Auto
CC	1496

#### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	1800043993-04

#### DRIVER

Name of Driver	Loh Tick Kwang
NRIC No	S7320285Z
Date Of Birth	09/06/1973
Occupation	Indoor



Date Of Driving Pass	25/07/2022
Driving experience	6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-84991358
Alt. Phone Number	-
Email Address	loh_tick_kwang@hotmail.com
Address	181 Edgefield Plains
Address complement	#06-240 SINGAPORE
Postcode	-
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	Yes
Vehicle Registration Number of Other Vehicle Owned by Driver	SLP5059Y
Insurance Company of Other Vehicle Owned by Driver	AIG Asia Pacific Insurance Pte. Ltd.

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### PASSENGER 1

Name	Seach Wee Choo
Gender	Female

#### PASSENGER 2

Name	Josh Loh Wei Zhao
Gender	Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

R2900009631      Circumstances Of Accident      Accident happened on 14 Jan 2022 at around 11.55am. I was driving along CTE towards SLE-TPE near the expressway exit toward SLE-TPE

near Lamppost 19A. Suddenly

a yellow comfortdelgro Taxi

SHC 994X hit onto the rear of my Car

a black Honda Jazz SLP5059Y

damaging the rear bumper

and the rear door. Both the driver's and passenger's head rest also damaged due to the whiplash caused by the impact. There were two passengers in my car

Seah Wee Choo and Josh Loh Wei Zhao (minor) and both did not have any visible injury. I got out of my car and exchanged details with Taxi driver

Teo Sa Wah of NRIC 0142243Z (Mobile 96724517)

of Yellow Taxi Car plate number SHC994X. He apologised and he didn't have any visible injury. After we exchanged of details

we drove off.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC994X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-96724517
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-





KV

Not Authorized

11/12/2020  
Accuracy After RepairLump Sum Repair  
less 20%**RIVERVIEW AUTO SERVICES PTE LTD**

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPOINT

SINGAPORE 568047

Tel : 6481 2025 / 6481 5797 Fax : 6481 8715

Email : service@riverviewauto.com.sg

Website : www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

SLP 5059Y Parts	Honda Jazz (2017)	List Price honda less 20%
Tailgate		R 730.80 ✓
Tailgate "Jazz" emblem		R 40 ✓
Tailgate inner lock		R 138.20 X
Tailgate inner trim board		R 296.70 X
Tailgate wiper motor		R 314 X
Tailgate shock absorbers x 2pc @ 187.70		R 375.40 X
Tailgate windscreen rubber moulding		R 112.40 ✓
Rear Bumper		R 483.50 ✓
Rear Bumper garnish cover RHS		R 60 X
Rear Bumper side retainer RHS		R 35 ✓
end panel lock catch		R 40 X
Rear end panel top garnish 125		R 131.20 ✓
Tailgate boot weatherstrip	6190 drilled	123.80 50% ✓
Rear end panel		R 401.80 ✓
Tail lamp RHS		R 287.50 ✓
Tailgate lock actuator sensor		R 188.20 X
Exhaust muffler 205		R 548.20 X
Special rmt. items		Nett Price
Tailgate Reverse Camera		R 450 X
Rear Bumper Reverse parking sensors (4pc set)	shot	400 200% ✓
Rear Bumper clips (1set)		R 35 ✓
Rear end panel sealant		R 100 30% ✓
Rear windscreen glass sealant		R 100 40% ✓



# RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPOINT

SINGAPORE 568047

Tel : 6481 2025 / 6481 5797 Fax : 6481 8715

Email : service@riverviewauto.com.sg

Website : www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum Repair  
Less 20%

SLP 50594

Honda Jazz

Labour charges

60d

1) To Renew & Repair Accident Area, Tailgate, Rear Bumper,  
Rear end panel, To panel beat and straighten  
Rear fender RHS. \$1500

12d

2) To Remove and Refit rear windscreen. \$200

3d

3) To Assemble Reverse camera and Reverse  
parking sensors, To check wiring and proper functions. \$100

60d

4) To spray paint Tailgate, Rear Bumper,  
Rear end panel, Rear fender RHS, Rear door RHS \$1500

6d

5) To carry out anti Rust treatment at the  
accident area on the affected panels. \$150

884h70

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: