

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ivy Yong

Date: 26 Jun 2023

Preliminary Advice

Vehicle No	: SJP26Z	Accident Date	: 13/01/2023
Make	: MERCEDES-BENZ S320L	Policy No.	: DMPG23000269
Assignment Date	: 17/01/2023	Excess	: S\$1,000.00
Date of Inspection	: 17/01/2023	Est. Duration of Repair	: 8
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,916.91	(Estimate \$18,272.03 + Supplementary \$644.88)
Revised Amount	:S\$	15,768.41	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	15,768.41	

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	318,000.00
COE / PARF Rebate	:S\$	129,491.00
Salvage Value	:S\$	
Margin for Repair	:S\$	188,509.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.