



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 2951L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	RH/ FRONT DOOR (SN)	BENT	2,111.02	2,111.02
1	RH/ FRONT DOOR SEAL (SN)	NECESSARY	317.72	317.72
1	RH/ FRONT DOOR ORNAMENTAL MOLDING (SN)	NECESSARY	123.46	123.46
1	RH/ FRONT DOOR ABSORBING (SN)	NECESSARY	74.42	74.42
1	RH/ FRONT DOOR TRIM STRIP (SN)	NOT NECESSARY	207.96	-
1	RH/ REAR DOOR (SN)	BENT	2,274.37	2,274.37
1	RH/ REAR DOOR SEAL (SN)	NECESSARY	317.72	317.72
1	RH/ REAR DOOR ORNAMENTAL MOLDING (SN)	NOT NECESSARY	149.84	-
1	RH/ REAR DOOR ABSORBING (SN)	NECESSARY	74.42	74.42
1	RH/ REAR DOOR GUARD PLATE (SN)	NECESSARY	36.44	36.44
1	RH/ REAR DOOR ORNAMENTAL TRIM (SN)	NOT NECESSARY	194.99	-
1	RH/ REAR DOOR 3/4 WINDOW (SN)	NOT NECESSARY	152.25	-
1	RH/ REAR DOOR ORNAMENTAL TRIM (SN)	NOT NECESSARY	341.69	-
1	RH/ RUNNING BOARD (SN)	NOT NECESSARY	341.69	-
1	RH/ RUNNING BOARD BRACKET (SN)	NOT NECESSARY	81.68	-
1	RH/ RUNNING BOARD BRACKET (SN)	NOT NECESSARY	78.54	-
1	RH/ REAR FENDER WHEEL ARCH TRIM (SN)	NOT NECESSARY	262.62	-
1	RH/ REAR SPOKE WHEEL (SN)	NOT NECESSARY	1,633.61	-
20	BLIND RIVET WITH PAD HEAD (SN) (ADDITIONAL)	NECESSARY	54.00	54.00
			<b>8,828.44</b>	<b>5,383.57</b>
<b><u>LABOUR</u></b>				
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.			1,920.00	1,920.00
RESPRAY RH/FRONT DOOR, RH/ REAR DOOR & RH/ REAR FENDER.			3,000.00	1,600.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.			380.00	380.00
REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR.			800.00	800.00
TO INSPECT & CONDUCT WHEEL ALIGNMENT.			540.00	-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER RIM AND BALANCING TYRE.	NOT NECESSARY	60.00	-
			6,700.00	4,700.00
<b>GRAND TOTAL</b>			<b>15,528.44</b>	<b>10,083.57</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>10,083.57</b>

Report Ref No. CS/SMR23000565/Rqy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.