



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKS2951L

MS FIRST CAPITAL INSURANCE LIMITED
MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information
WIP No **62461**
Reg No/Reg Date **SKS2951L / 02/04/2015**
Date In/Mileage **06/02/2023/ 112415**
Chassis No **WDC1569432J020338**
Engine No **27091030414724**
Make/Model **MB/GLA 200 B/E OFFROADER (X1**
Colour/Trim **027 761 Polar Silv/ 046 651 DINAMICA/AR**

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	10/02/2023/ 14:36		301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 2100407769-07 // 11/01/2023 DRIVE IN/TP VEHICLE NO. : 17/01/2023 // SHB1801T - FIRST CAPITAL DATE IN/DATE SURVEY: 06/02/2023 1205 // LKK - RASUL DIRECT SETTLEMENT : 26/01/2023 // FIRST CAPITAL - Karen Tan				1920.00
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.			0.05	1600.00
A BPIRES RESPRAY RH/ FRONT DOOR & RH/ REAR DOOR			0.10	380.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.05	800.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT	1.00	2111.02	00.00	2111.02
X RH/ FRONT DOOR	1.00	317.72	00.00	317.72
X RH/ FRONT DOOR SEAL	1.00	123.46	00.00	123.46
X RH/ FRONT DOOR ORNAMENTAL MOLDING	1.00	74.42	00.00	74.42
X RH/ FRONT DOOR ABSORBING	1.00	2274.37	00.00	2274.37
X RH/ REAR DOOR	1.00	317.72	00.00	317.72
X RH/ REAR DOOR SEAL	1.00	74.42	00.00	74.42
X RH/ REAR DOOR ABSORBING	1.00	36.44	00.00	36.44
X RH/ REAR DOOR GUARD PLATE	1.00	36.44	00.00	36.44
X BLIND RIVET WITH PAN HEAD	20.00	2.70	00.00	54.00

Finalization

Confirmed & accepted by

Nett	10,083.57
8% GST on	10083.57
Total Payable	10,890.26

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKS2951L

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No **62461**
Reg No/Reg Date **SKS2951L / 02/04/2015**
Date In/Mileage **06/02/2023/ 112415**
Chassis No **WDC1569432J020338**
Engine No **27091030414724**
Make/Model **MB/GLA 200 B/E OFFROADER (X1**
Colour/Trim **027 761 Polar Silv/ 046 651 DINAMICA/AR**

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WF001862	Credit	10/02/2023/ 14:35	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X BLIND RIVET WITH PAN HEAD					20.00	2.70	00.00	54.00

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

	Nett	54.00
8% GST on	54.00	4.32
	Total Payable	58.32

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg