



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKS2951L

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No: 62461
Reg No/Reg Date: SKS2951L / 02/04/2015
Date In/Mileage: / 0
Chassis No: WDC1569432J020338
Engine No: 27091030414724
Make/Model: MB/GLA 200 B/E OFFROADER (X1)
Colour/Trim: 027 761 Polar Silv/ 046 651 DINAMICA/AR

SKS2951L

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	17/01/2023/ 11:15	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M-BPNSUN				
POLICY NO/ACC DATE : 2100407769-07 // 11/01/2023				
DRIVE IN/TP VEHICLE NO. : 17/01/2023 // SHB1801T - FIRST CAPITAL				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
A BPILAB				1920.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES				1600 3000.00
RESPRAY RH/ FRONT DOOR, RH/ REAR DOOR & RH/ REAR FENDER				
A BPILAB	0.10			380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
A BPILAB	0.05			800.00
REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR.NETT				
A BPILAB				540.00
TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				
S BPNSUB				60.00
TRANSFER RIM AND BALANCING TYRE. NETT				
PURCHASE ORDER NO:				
M RH/ FRONT DOOR	1.00	2111.02	00.00	2111.02
M RH/ FRONT DOOR SEAL	1.00	317.72	00.00	317.72
M RH/ FRONT DOOR ORNAMENTAL MOLDING	1.00	123.46	00.00	123.46
M RH/ FRONT DOOR ABSORBING	1.00	74.42	00.00	74.42
M RH/ FRONT DOOR TRIM STRIP	1.00	207.96	00.00	207.96
M RH/ REAR DOOR	1.00	2274.37	00.00	2274.37
M RH/ REAR DOOR SEAL	1.00	317.72	00.00	317.72
M RH/ REAR DOOR ORNAMENTAL MOLDING	1.00	149.84	00.00	149.84
M RH/ REAR DOOR ABSORBING	1.00	74.42	00.00	74.42
M RH/ REAR DOOR GUARD PLATE	1.00	36.44	00.00	36.44
M RH/ REAR DOOR ORNAMENTAL TRIM	1.00	194.99	00.00	194.99
M RH/ REAR DOOR 3/4 WINDOW	1.00	152.25	00.00	152.25

ESTIMATE

Confirmed & accepted by

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKS2951L

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 62461
Reg No/Reg Date SKS2951L / 02/04/2015
Date In/Mileage / 0
Chassis No WDC1569432J020338
Engine No 27091030414724
Make/Model MB/GLA 200 B/E OFFROADER (X1
Colour/Trim 027 761 Polar Silv/ 046 651 DINAMICA/AR

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	17/01/2023/ 11:15	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RH/ REAR DOOR ORNAMENTAL TRIM <i>X n</i>	1.00	341.69	00.00	341.69
M RH/ RUNNING BOARD <i>X n</i>	1.00	341.69	00.00	341.69
M RH/ RUNNING BOARD BRACKET <i>X n</i>	1.00	81.68	00.00	81.68
M RH/ RUNNING BOARD BRACKET <i>X n</i>	1.00	78.54	00.00	78.54
M RH/ REAR FENDER WHEEL ARCH TRIM <i>see X n</i>	1.00	262.62	00.00	262.62
M RH/ REAR SPOKE WHEEL <i>X n</i>	1.00	1633.61	00.00	1633.61

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Panel
Hp 90010068
5 days
20/06/23 @ 12:00
Resy before paint

Confirmed & accepted by

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Nett	15,474.44
8% GST on	15474.44
Total Payable	16,712.40

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378