



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE		Ref: CC4/ASM23000567/Apa3q2 Date: 20/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2207H	Veh. Inspected	SMZ 959T
Policy No.	P2478218	Coverage (\$)	0.00
Claim No.	S3M04I11	Excess (\$)	0.00
Assign From		Assign Date	16/01/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ESQUIRE	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZRR800173525	Colour	WHITE
Odometer	82432 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	TOURADOR	6 mm
L/H Front Tyre	215/55 R17	TOURADOR	6 mm
R/H Rear Tyre	215/55 R17	TOURADOR	6 mm
L/H Rear Tyre	215/55 R17	TOURADOR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/01/2023	Inspection Date	16/01/2023
Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	