

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

TP AxA.

Xiao Tony

16-Jan-23

Our ref : TP/5220/23

ZIRR800173525

Chew Soon Hock Edwin

RE : estimate cost for vehicle no : SMZ 959T

1 pc	tailgate <i>Distorted</i>	\$	1,900.00 ✓
1 pc	tailgate lock <i>2nd</i>		452.00 ✓
1 pc	Esquire emblem <i>new</i>		49.70 ✓
1 pc	tailgate w/strip <i>cut</i>		372.30 ✓
1 pc	tailgate trimboard <i>could</i>		570.30 ✓
1 pc	rear no plate lamp <i>new</i>		140.60 x
1 pc	tailgate outer garnish <i>new</i>		861.20 +
1 pc	tailgate inner handle <i>new</i>		32.54 +
1 pc	tailgate stopper top <i>could</i>		51.40 ✓
1 pc	tailgate stopper lower <i>new</i>		38.60 +
1 pc	rear bumper <i>Delid</i>		745.50 ✓
2 pcs	taillamp <i>cut</i>		1,405.60 ✓
2 pcs	rear bumper reflector <i>LH cracked</i>		119.60 <i>39.80</i>
2 pcs	rear bumper retainer long <i>LH 2nd</i>		321.40 <i>160.70</i>
2 pcs	rear bumper retainer short <i>Delid</i>		147.20 <i>73.60</i>
1 pc	rear bumper tow hook cover <i>Delid</i>	8807.60	47.70 ✓
6 pcs	rear bumper clips <i>new</i>		30.00 ✓
1 pc	rear bumper side lh <i>Delid</i>	6605.70	176.80 ✓
1 pc	end panel <i>Distorted</i>		935.70 ✓
1 pc	end panel inner garnish <i>Delid</i>		252.90 ✓
1 pc	spare tyre panel <i>Repair</i>		998.70 x
1 pc	spare tyre cardboard <i>could</i>		1,141.00 <i>785</i>
1 pc	spare tyre carpet <i>new</i>		568.90 x
2 pcs	rear fender inner trim <i>LH Delid</i>		1,164.40 <i>582.20</i>
1 pc	key lock sensor <i>2nd</i>		156.40 ✓
1 pc	bluzzer <i>new</i>		129.60 +
			12,810.04
less 25%			3,202.51
			9,607.53
1 pc	reverse sensor <i>David</i>		250.00 <i>snett 200</i>
1 pc	rear bumper chrome <i>Delid</i>		350.00 <i>280</i>
1 pc	rear no plate <i>Delid</i>	600	40.00 ✓
1 pc	rea w/screen gum <i>2nd</i>		50.00 ✓
1 pc	rear w/screen seal <i>new</i>		30.00 ✓
			10,327.53

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : SMZ 959T

Bal brought forward: \$ 10,327.53

1 pc camera	450.00	x.
Panel beating.	1,200.00	1000
Spray painting.	1,200.00	800
Wiring.	30.00	✓
Remove & refit rear w/screen .	150.00	120
Transfer tailgate fitting.	80.00	✓
Upholstery.	120.00	80
Rust proofing.	120.00	80
Alignment.	80.00	x.
	13,677.53	
Plus 8% GST	1,094.20	
	14,771.73	

SD : fourteen thousand seven hundred seventy-one & cents seventy-three only.

Adrian G

h/s 16/01/23.

06 Days.

total: 9495.70

h/s : 7-61C

7-61C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: