

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Vehicle No : SME1743C

Chassis No: ZWR800334382

Make/Model : TOYOTA NOAH

Accident date : 17.01.2023

TP AXA
Xiao Tay

No	DESCRIPTION	Qty	Amount (\$S)
<u>List Items</u>			
1	Rear windscreen rubber <i>Hee</i>	1	\$ 312.50 <i>185.</i>
2	Rear tailgate <i>Dented</i>	1	\$ 2,083.90 <i>1738.</i>
3	Rear tailgate "Hybrid" emblem <i>new</i>	1	\$ 150.80 <i>-</i>
4	Rear tailgate side moulding <i>new</i>	1	\$ 92.00 <i>-</i>
5	Rear tailgate hinges @ \$312.50	2	\$ 625.00 <i>+</i>
6	Rear tailgate shock absorber @ \$439.20 <i>2 new</i>	2	\$ 878.40 <i>+</i>
7	Rear tailgate inner board <i>Hee</i>	1	\$ 898.70 <i>+</i>
8	Rear tailgate upper lock <i>Damaged</i>	1	\$ 657.50 <i>385.</i>
9	Rear tailgate lower lock <i>new</i>	1	\$ 311.80 <i>+</i>
10	Rear tailgate weather strip <i>new</i>	1	\$ 426.90 <i>+</i>
11	Rear end panel <i>Repair</i>	1	\$ 899.20 <i>+</i>
12	Rear end panel top garnish <i>new</i>	1	\$ 426.90 <i>+</i>
13	Rear bumper <i>Dented</i>	1	\$ 986 <i>-</i>
14	Rear bumper reflector @ \$196.80 <i>new</i>	2	\$ 393.60 <i>+</i>
			\$ 8,711.40
			Less 25% Disc \$ 2,177.85
			Total \$ 6,533.55

3530.80

2648.10

Special Nett Items

1	Rear bumper reverse sensor <i>Damaged</i>	2	\$ 380.00 <i>200.</i>
2	Rear bumper clips (1 set) <i>new</i>	1	\$ 60.00 <i>30.</i>
			Total \$ 440.00

230

Labour Cost

1	To supply rear windscreen sealant	\$ 50.00 <i>✓</i>
2	Remove & refix rear windscreen	\$ 180.00 <i>120.</i>
3	Remove & refix reverse sensor	\$ 150.00 <i>50.</i>
4	Remove, replace & repair consistent to the accident	\$ 1,100.00 <i>400.</i>
5	Respray painting	\$ 1,000.00 <i>400.</i>
		Total \$ 2,480.00

1020

Grand Total

\$ 9,453.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3898.10

h/s: 3.1K.

3.1K