

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0066/2023/EQ
DATE : 17-Jan-23
WIP : 59356

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/1/2023

YOUR INSURED VEH NO : SDJ 87 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR OLIVEIRO GLEN NEVILLE
ADDRESS : 84 RIVERINA VIEW
SINGAPORE 518433

TELEPHONE : HP +65 81234897
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100505829
VEHICLE NO : **SFF 1520 G**
MODEL CODE : AUDI A6 1.8 TFSI S-TRONIC
MODEL YEAR : 31/3/2017
ENGINE NO : CYG 017684
CHASSIS NO : WAUZZZ4G6HN061552
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Jan-23
PLACE OF ACCIDENT : KPE TOWARDS ECP 8.3KM MARK LANE 1 ACCIDENT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFF 1520 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	
3	TO RESPRAY REAR BUMPER.	\$	1,000.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFF 1520 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 3,677.00	
2	REAR BUMPER FIXING PARTS	1	\$ 301.00	
3	REAR BUMPER SPOILER	1	\$ 565.00	
4	REAR BUMPER SECURING STRIP	1	\$ 264.00	
5	REAR BUMPER CLOSING ELEMENT - LH / RH	2	\$ 190.00	
6	EXHAUST TAIL PIPE TRIM - LH / RH	2	\$ 1,300.00	
7	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,140.00	
8	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 34.00	
9	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 78.00	
10	REAR BUMPER GUIDE SECTION - LH / RH LOWER	2	\$ 126.00	
11	REAR BUMPER GUIDE PROFILE - LH / RH	2	\$ 158.00	
12	REAR BUMPER GUIDE SECTION - CENTER	1	\$ 126.00	
13	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 152.00	
14	REAR PARKING AID SENSOR - INNER / OUTER	3	\$ 815.00	
15	REAR PARKING AID SEAL RING	4	\$ 6.00	
16	REAR BOOT LID OPENING CONTROL UNIT	1	\$ 528.00	
17	REAR BOOT LID OPENING CONTROL UNIT RETAINER	1	\$ 10.00	
18	REAR TAILGATE OPENING SENSOR LINE	1	\$ 230.00	
19	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 10,100.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	
GRAND TOTAL		:	\$ 12,852.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT