

ASS. REC. BY:

REF:

C12 / 23000572/KP

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1-B,1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PN6 945X Yr Regn: 07 22Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy A1715 c.c. 1798Colour: M. Blue A/C: Insured / Std / NI / NASp. Reading: 48693 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR 23 83B E 400009527Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: APL5 225/45R17R: B.1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 6 mmL/Bal. 8 mmL/Bal. 6 mmD.O.A. 12/1/23D.O.I. 16/1/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

o/s body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

7/3 Z/Smp @ 3800 Cuh

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Date: 16/01/2023
Vehicle No: SNG945X
Model: TOYOTA COROLLA ALTIS 4DR SEDAN HYBRID
Chassis: MR2BZ3BE400009527-2022
Reg.Year: 2022

Not Notified
Resurvey B&P.M
4 days
L1 Rmp @ 3800ph

Third Party Insurer: CHINA TAIPING
Third Party Veh No: XE6961B
Date of Accident: 12/01/2023
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH <i>1150</i>	1		<i>R</i> \$1,359.00
2	FRONT DOOR INNER TRIM BOARD RH <i>980</i>	1		<i>mgent</i> \$1,298.00
3	FRONT DOOR WEATHERSTRIP RH	1		<i>sm</i> \$262.00
4	REAR DOOR RH <i>1150</i>	1		<i>R</i> \$1,180.00
5	REAR DOOR INNER TRIM BOARD RH	1		<i>sm</i> \$1,142.00
6	REAR DOOR UPPER HINGE RH	1		<i>R</i> \$90.00
7	REAR DOOR LOWER HINGE RH	1		<i>DIT</i> \$117.00
8	REAR DOOR CHECKER RH	1		<i>sm</i> \$199.00
9	REAR DOOR WINDOW REGULATOR RH <i>279</i>	1		<i>DIT</i> \$431.00
10	REAR DOOR WINDOW MOTOR RH	1		<i>sm</i> \$668.00
11	REAR DOOR INNER LOCK RH <i>591</i>	1		<i>nd</i> \$675.00
12	REAR DOOR OUTER MOULDING RH	1		<i>DIT</i> \$107.00
13	REAR DOOR FRAME GARNISH COVER RH	1		<i>sm</i> \$60.00
14	REAR FENDER QUARTER GARNISH COVER RH	1		<i>mgent</i> \$60.00
SUB TOTAL				\$7,648.00
LESS 25%				-\$1,912.00
PARTS TOTAL				\$5,736.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR INNER TRIM BOARD CLIPS RH	1		<i>nn</i> \$50.00
2	REAR DOOR INNER TRIM BOARD CLIPS RH	1		<i>nn</i> \$50.00
S/N TOTAL				\$100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Acknowledged by Repairer

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 16/01/2023
Vehicle No: SNG945X
Model: TOYOTA COROLLA ALTIS 4DR SEDAN HYBRID
Chassis: MR2BZ3BE400009527-2022
Reg.Year: 2022

Third Party Insurer: CHINA TAIPING
Third Party Veh No: XE6961B
Date of Accident: 12/01/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

4001
\$500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR RH, REAR DOOR RH & ETC.

4001
\$500.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.

601
\$120.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.

601
\$120.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

nn \$150.00

TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC.

201
\$120.00

LABOUR TOTAL \$1,510.00

TOTAL \$7,346.00

TING AN

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1983

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

