

Date: 16/01/2023

Vehicle No: SNG945X

Model: TOYOTA COROLLA ALTIS 4DR SEDAN HYBRID

Chassis: MR2BZ3BE400009527-2022

Reg.Year: 2022

Third Party Insurer: CHINA TAIPING

Third Party Veh No: XE6961B

Date of Accident: 12/01/2023

Estimator: TING AN

Surveyor:

Not With Claim

Return B & Pains

4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH	1		<i>R</i> \$1,359.00 ✓
2	FRONT DOOR INNER TRIM BOARD RH	1		\$1,298.00 7
3	FRONT DOOR WEATHERSTRIP RH	1		\$262.00 7
4	REAR DOOR RH	1		<i>R</i> \$1,180.00 ✓
5	REAR DOOR INNER TRIM BOARD RH	1		<i>in</i> \$1,142.00 X
6	REAR DOOR UPPER HINGE RH	1		<i>R</i> \$90.00 ✓
7	REAR DOOR LOWER HINGE RH	1		<i>Di</i> \$117.00 ✓
8	REAR DOOR CHECKER RH	1		\$199.00 7
9	REAR DOOR WINDOW REGULATOR RH	1		\$431.00 7
10	REAR DOOR WINDOW MOTOR RH	1		\$668.00 7
11	REAR DOOR INNER LOCK RH	1		\$675.00 7
12	REAR DOOR OUTER MOULDING RH	1		<i>Di</i> \$107.00 ✓
13	REAR DOOR FRAME GARNISH COVER RH	1		<i>R</i> \$60.00 X
14	REAR FENDER QUARTER GARNISH COVER RH	1		\$60.00 7
SUB TOTAL				\$7,648.00
LESS 25%				-\$1,912.00
PARTS TOTAL				\$5,736.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR INNER TRIM BOARD CLIPS RH	1		<i>nn</i> \$50.00 X
2	REAR DOOR INNER TRIM BOARD CLIPS RH	1		\$50.00 7
S/N TOTAL				\$100.00

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011



Date:	16/01/2023	Third Party Insurer:	CHINA TAIPING
Vehicle No:	SNG945X	Third Party Veh No:	XE6961B
Model:	TOYOTA COROLLA ALTIS 4DR SEDAN HYBRID	Date of Accident:	12/01/2023
Chassis:	MR2BZ3BE400009527-2022	Estimator:	TING AN
Reg.Year:	2022	Surveyor:	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

400
\$500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR RH, REAR DOOR RH & ETC.

400
\$500.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.

60
\$120.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.

60
\$120.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

150
\$150.00


TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC.

120
\$120.00

LABOUR TOTAL \$1,510.00

TING AN

TOTAL \$7,346.00



Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

