



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2304674

INV Date 20/07/2023

Reference CC4/LPC23000574/Tpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLF 5921K
Insured Veh. GBG 624P
Claim No. 22/23/23/VC05/026800
Policy No. Z22VC05011592
Accident Date 03/01/2023
Inspection Date 18/01/2023

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC23000574/Tpa3q2 Date: 20/07/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 624P	Veh. Inspected	SLF 5921K	
Policy No.	Z22VC05011592	Coverage (\$)	0.00	
Claim No.	22/23/23/VC05/026800	Excess (\$)	0.00	
Assign From	ENG HUEY NI	Assign Date	17/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	NSP1707046806	Colour	WHITE	
Odometer	256717 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/01/2023	Inspection Date	18/01/2023	
Survey held at	MOHAMMAD AUTOMOBILE No. 38, Woodlands Industrial Park E-1, #01-16, Singapore 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5921K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	BENT	890.00	890.00
1	BOOTLID LOGO (TOYOTA)	NECESSARY	68.00	68.00
1	BOOTLID HANDLE	CRACKED	165.00	165.00
2	BOOTLID HYDAULIC CYLINDERS L&R @\$186.00	NOT NECESSARY	372.00	-
1	BOOTLID LOCK CYLINDER	NOT NECESSARY	197.00	-
2	BOOTLID NUMBER PLATE LAMP L/R @\$46.00	NOT NECESSARY	92.00	-
1	BOOTLID INNER TRIM	NOT NECESSARY	259.00	-
2	BOOTLID HINGE L/R @\$87.00	NOT NECESSARY	174.00	-
1	BOOTLID LOCK	BENT	186.00	186.00
1	BOOTLID LOCK CATCH	NOT NECESSARY	93.00	-
1	BOOTLID WEATHERSTRIP	TORN	180.00	180.00
1	BOOTLID WIND SCREEN	NOT NECESSARY	480.00	-
1	REAR BUMPER	DEFORMED	685.00	685.00
2	REAR BUMPER REFLECTOR L/R @\$115.00	NOT NECESSARY	230.00	-
2	REAR BUMPER RETAINER L/R @\$65.80	DEFORMED	131.60	131.60
1	REAR BUMPER REINFORCEMENT BAR	NOT NECESSARY	376.00	-
1	END PANEL	BENT	788.00	430.00
1	END PANEL GARNISH	DEFORMED	136.70	136.70
1	SPARE WHEEL PANEL	TO REPAIR SEE LABOUR	681.00	-
	LESS 25% DISCOUNT		-1,546.08	-718.08
			4,638.22	2,154.22
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
1	BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
1	TAIL LAMP PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	END PANEL GARNISH CLIPS (SN)	NECESSARY	50.00	20.00

Report Ref No. CC4/LPC23000574/Tpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE WHEEL PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
			750.00	250.00
	LABOUR			
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING ,REPLACED ,DAMAGED LAMP AND TEST FOR PROPER FUNCTIONING.		100.00	30.00
	TO REMOVE AND REFIT REAR CUSHION SEATS, INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR .		120.00	60.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR .		80.00	30.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF SPARE WHEEL PANEL .		1,800.00	600.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,800.00	600.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACE PANELS FOR RUST PROTECTION .		120.00	30.00
			4,020.00	1,350.00
GRAND TOTAL			9,408.22	3,754.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC4/LPC23000574/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

