

吉维利企业 **KIVILE ENTERPRISE**

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2533

EMAIL: kivilepc@gmail.com

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBP711L

Model: YAMAHA LC135

Description

Handlebar	\$	105 ? Dent /
Handlebar Holder	\$	65 ? Dent /
Mirror	\$	85 Sur 70
Balancer	\$	45 Sur /
Clutch Lever	\$	75 XNNX
Brake Lever	\$	75 Sur /
Cover set	\$	600 Br 250
Front Signal LH	\$	65 Br 50
Fork set	\$	280 ? Dent /
Fork Lower Clamp	\$	280 ? Dent 120
Steering Cone	\$	110 ? Dent 55
Rim	\$	480 ? Dent /
Disc	\$	160 ? Dent 90
Wheelshaft	\$	135 ? Dent 60
Radiator	\$	280 Sur /
Coolant Pump	\$	280 Br 80
Coolant Hose	\$	45 Lvx 30
Coolant Reservoir	\$	90 Br 60
Gear Pedal	\$	75 Br 50
Front footrest	\$	85 Br /
Footrest rubber	\$	65 Br 20
Sidestand	\$	110 ? Sur 80
Engine Cover LH	\$	180 Sur 90
Brake Pedal	\$	60 Sur /
Exhaust Pipe Yoshi	\$	1,280 Sur /
Front Basket	\$	75 Dent 50
Front Garnish	\$	75 Nec 40
Center Fairing	\$	125 ? Br 60
Rearbox	\$	280 Sur 150
Body Frame Repair	\$	380 ? 300
Paintwork	\$	220 XN/V
Front Number Plate	\$	30 mss 10
Labour	\$	600 400
Towing	\$	50 30

TOTAL \$ **6,945**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Comp

Acknowledged by Repairer

Signature:

Date:

Parts = 4000
10% = 400
= 3600
\$3,744.00

3 days

1 rfm L/S

Total: 4340 4454.00
20% = 868 3,563.20
= 3476

19/1/23

2pm