

SERVICE ESTIMATE

89075 - C00001 SL: SERVICE SALES - PC

Mr Lee Yuan Cherng
BLK 650A Jurong West Street 61
#13-272

Singapore 641650

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Lee Yuan Cherng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 17/01/2023
WIP No. . : 59380
Veh.In/Out:
*Tel.No. . : Mobile: 90225451
Reg.No. . : SLM2560B
Reg.date . : 24/03/2017
Mileage .. : 0
Chassis No: VF1RFB00156852524

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE BOOTLID, @ 550 X2	0	2200.00	0		2,200.00	S
	BOOTLID LOCK, LATCH, LOGO, RR BUMPER, RR LOWER COVER, FOG LAMP LH/RH, SENSORS, ETC					1100	
800	TO SPRAY BOOTLID, RR BUMPER @ 800 X2	0	1500.00	0		1,500.00	S
280	TO CHECK WIRING INCLUDE	0	450.00	0		450.00	S
	RESETTING OF ALL ELECTRICAL MODULES						
R06	NUMBER PLATE & HOLDER	0	60.00	0		60.00	S
	BOOT ASSY M4S	1.0 EA	1950.00			1,950.00	S
	BOOT OUTER PANEL WIT	1.0 EA	1042.00			1,042.00	S
	BOOT SWITCH M4S	1.0 EA	137.70			137.70	S
	BOOT SWITCH COVER M4	1.0 EA	29.40			29.40	S
	EMBLEM "MEGANE" REAR	1.0 EA	132.60			132.60	S
	LOGO REAR M4S	1.0 EA	184.90			184.90	S
	BOOT LOCK ASSY M4S	1.0 EA	256.80			256.80	S
	BOOT SEAL REAR M4S	1.0 EA	245.40			245.40	S

SERVICE ESTIMATE

89075 - C00001 SL: SERVICE SALES - PC
 Mr Lee Yuan Cherng
 BLK 650A Jurong West Street 61
 #13-272

Singapore 641650

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : Mr Lee Yuan Cherng

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 2
 Inv.date. : 17/01/2023
 WIP No. . : 59380
 Veh.In/Out:
 *Tel.No. . : Mobile: 90225451
 Reg.No. . : SLM2560B
 Reg.date . : 24/03/2017
 Mileage . : 0
 Chassis No: VF1RFB00156852524

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	BOOT LAMP-REAR RH M4 <i>X¹⁷</i>	1.0	EA	503.40			503.40	S
	BOOT LAMP REAR LH M4 <i>X¹⁷</i>	1.0	EA	503.40			503.40	S
	NUMBER PLATE LAMP GS <i>? X¹⁷</i>	2.0	EA	31.30			62.60	S
	LAMP-FOG, REAR RH GS <i>X¹⁷</i>	1.0	EA	254.50			254.50	S
	LAMP FOG, REAR LH GS <i>X¹⁷</i>	1.0	EA	254.50			254.50	S
	BUMPER REAR M4S <i>der</i>	1.0	EA	956.20		<i>860.58</i>	956.20	S
	TOW COVER RR M4S <i>X¹⁷</i>	1.0	EA	94.00			94.00	S
	BUMPER PAD LOWER M4S <i>sur</i>	1.0	EA	429.30		<i>386.37</i>	429.30	S
	BUMPER REAR OUTER SI <i>X¹⁷</i>	1.0	EA	241.90			241.90	S
	BUMPER RR SIDE TRIM <i>X¹⁷</i>	1.0	EA	98.00			98.00	S
	BUMPER REAR INNER SI <i>? X¹⁷</i>	1.0	EA	231.30			231.30	S
	BUMPER REAR SIDE SUP <i>X¹⁷</i>	1.0	EA	352.50			352.50	S
	BUMPER CENTER BRACKE <i>? X¹⁷</i>	1.0	EA	150.70			150.70	S
	BUMPER REAR INNER PL <i>? X¹⁷</i>	1.0	EA	519.80			519.80	S
	BOOT CAMERA-RR M4S <i>X¹⁷</i>	1.0	EA	457.00			457.00	S
	PARK SENSOR BOTH CTR <i>? X¹⁷</i>	2.0	EA	557.20			1,114.40	S
	BUMPER UNDER COVER I <i>? X¹⁷</i>	1.0	EA	400.00			400.00	S

SERVICE ESTIMATE

89075 - C00001 SL: SERVICE SALES - PC
 Mr Lee Yuan Cherng
 BLK 650A Jurong West Street 61
 #13-272

Singapore 641650

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : Mr Lee Yuan Cherng

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 3
 Inv.date. : 17/01/2023
 WIP No. . : 59380
 Veh.In/Out:
 *Tel.No. . : Mobile: 90225451
 Reg.No. . : SLM2560B
 Reg.date . : 24/03/2017
 Mileage . : 0
 Chassis No: VF1RFB00156852524

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER UNDER INNER C ? <i>Xnn</i>	1.0 EA	294.00			294.00	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- All prices are subject to confirmation
- All work is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer

Signature

Date:

Form
Hp 90010068
(4 days)
18/01/23 @ 1150
Reg before print

Labour Total 4,210.00
 Parts Total 10,896.30
 Package Total 0.00

Gross Total. 15,106.30
 Net..... 15,106.30
 GST @ 8.0% 1,208.50
 Total..... 16,314.80
 Paid..... 0.00
 Please Pay.. 16,314.80

GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate

SERVICE ESTIMATE

89075 - C00001 SL: SERVICE SALES - PC

Mr Lee Yuan Cherng
BLK 650A Jurong West Street 61
#13-272

Singapore 641650

Closed by : Juan Paulo Bongon Ba
Svc Consultant : ACC
Remarks : Mr Lee Yuan Cherng

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 14/02/2023

WIP No. . : 59380

Veh.In/Out: 08/02/2023

*Tel.No. . : Mobile: 90225451

Reg.No. . : SLM2560B

Reg.date . : 24/03/2017

Mileage .. : 81,465

Chassis No: VF1RFB00156852524

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPAIR REAR END PANEL	0	550.00	0		550.00	S
800	TO SPRAY REAR END PANEL,	0	1000.00	0		1,000.00	S
REAR FENDER LH							
	BOOT LOCK ASSY M4S	1.0 EA	256.80			256.80	S 231.62
	NUMBER PLATE LAMP GS	1.0 EA	31.30			31.30	S 28.17
	BOOT INNER INSULATOR	1.0 EA	719.40			719.40	S 647.46

Suppl

			Gross Total.	2,557.50
Labour	Total	1,550.00	Net.....	2,557.50
Parts	Total	1,007.50	GST @ 8.0%	204.60
Package	Total	0.00	Total.....	2,762.10
			Paid.....	0.00
			Please Pay..	2,762.10

GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate