

SERVICE ESTIMATE

89075 - C00001 SL: SERVICE SALES - PC

Mr Lee Yuan Cherng
BLK 650A Jurong West Street 61
#13-272

Singapore 641650

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Lee Yuan Cherng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 17/01/2023
WIP No. . : 59380
Veh.In/Out:
*Tel.No. . : Mobile: 90225451
Reg.No. . : SLM2560B
Reg.date . : 24/03/2017
Mileage .. : 0
Chassis No: VF1RFB00156852524

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE BOOTLID, BOOTLID LOCK, LATCH, LOGO, RR BUMPER, RR LOWER COVER, FOG LAMP LH/RH, SENSORS, ETC	0	2200.00	0		2,200.00	S
800	TO SPRAY BOOTLID, RR BUMPER	0	1500.00	0		1,500.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S
R06	NUMBER PLATE & HOLDER	0	60.00	0		60.00	S
	BOOT ASSY M4S	1.0 EA	1950.00			1,950.00	S
	BOOT OUTER PANEL WIT	1.0 EA	1042.00			1,042.00	S
	BOOT SWITCH M4S	1.0 EA	137.70			137.70	S
	BOOT SWITCH COVER M4	1.0 EA	29.40			29.40	S
	EMBLEM "MEGANE" REAR	1.0 EA	132.60			132.60	S
	LOGO REAR M4S	1.0 EA	184.90			184.90	S
	BOOT LOCK ASSY M4S	1.0 EA	256.80			256.80	S
	BOOT SEAL REAR M4S O	1.0 EA	245.40			245.40	S

SERVICE ESTIMATE

89075 - C00001 SL: SERVICE SALES - PC

Mr Lee Yuan Cherng
BLK 650A Jurong West Street 61
#13-272

Singapore 641650

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Lee Yuan Cherng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 17/01/2023
WIP No. . : 59380
Veh.In/Out:
*Tel.No. . : Mobile: 90225451
Reg.No. . : SLM2560B
Reg.date . : 24/03/2017
Mileage .. : 0
Chassis No: VF1RFB00156852524

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BOOT LAMP-REAR RH M4	1.0 EA	503.40			503.40	S
	BOOT LAMP REAR LH M4	1.0 EA	503.40			503.40	S
	NUMBER PLATE LAMP GS	2.0 EA	31.30			62.60	S
	LAMP-FOG, REAR RH GS	1.0 EA	254.50			254.50	S
	LAMP FOG, REAR LH GS	1.0 EA	254.50			254.50	S
	BUMPER REAR M4S	1.0 EA	956.20			956.20	S
	TOW COVER RR M4S	1.0 EA	94.00			94.00	S
	BUMPER PAD LOWER M4S	1.0 EA	429.30			429.30	S
	BUMPER REAR OUTER SI	1.0 EA	241.90			241.90	S
	BUMPER RR SIDE TRIM	1.0 EA	98.00			98.00	S
	BUMPER REAR INNER SI	1.0 EA	231.30			231.30	S
	BUMPER REAR SIDE SUP	1.0 EA	352.50			352.50	S
	BUMPER CENTER BRACKE	1.0 EA	150.70			150.70	S
	BUMPER REAR INNER PL	1.0 EA	519.80			519.80	S
	BOOT CAMERA-RR M4S	1.0 EA	457.00			457.00	S
	PARK SENSOR BOTH CTR	2.0 EA	557.20			1,114.40	S
	BUMPER UNDER COVER I	1.0 EA	400.00			400.00	S

SERVICE ESTIMATE

89075 - C00001 SL: SERVICE SALES - PC

Mr Lee Yuan Cherng
 BLK 650A Jurong West Street 61
 #13-272

Singapore 641650

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : Mr Lee Yuan Cherng

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 3
 Inv.date. : 17/01/2023
 WIP No. . : 59380
 Veh.In/Out:
 *Tel.No. . : Mobile: 90225451
 Reg.No. . : SLM2560B
 Reg.date . : 24/03/2017
 Mileage .. : 0
 Chassis No: VF1RFB00156852524

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER UNDER INNER C	1.0 EA	294.00			294.00	S

			Gross Total.	15,106.30
Labour Total	4,210.00	Net.....	15,106.30	
Parts Total	10,896.30	GST @ 8.0%	1,208.50	
Package Total	0.00	Total.....	16,314.80	
			Paid.....	0.00
			Please Pay..	16,314.80
GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate				