

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 16.01.2023

TO : LONPAC MOTOR CLAIMS DEPTS
VEHICLE NO : PC5747R
MODEL : TOYOTA HIACE
DATE OF ACCIDENT : 16.01.2023
TIME OF ACCIDENT : 08:15 HOURS

Xiao Tong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR SIDE PANEL LH <i>Dented</i>	1	\$ 2,984.00	\$ 2,984.00
2	REAR SIDE PANEL GLASS LH <i>Shattered</i>	1	\$ 1,310.10	\$ 1,310.10
3	REAR SIDE INNER PANEL LH <i>Refr</i>	1	\$ 1,895.20	\$ 1,895.20
4	REAR SIDE PANEL INNER TRIM LH <i>Just</i>	1	\$ 458.20	\$ 458.20
5	REAR SIDE PANEL INNER UPPER TRIM LH	1	\$ 295.60	\$ 295.60
4	TAIL LAMP LH <i>Xhe nu</i>	1	\$ 390.00	\$ 390.00

TOTAL PRICE \$ 7,333.10
LESS 25% \$ 1,833.28
SUB TOTAL PRICE \$ 5,499.83

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR SIDE PANEL SEALANT LH <i>Na</i>	1	\$ 150.00	\$ 150.00
2	REAR SIDE INNER PANEL SEALANT LH <i>Xhe nu</i>	1	\$ 150.00	\$ 150.00
3	REAR SIDE PANEL INNER TRIM CLIP LH (SET) <i>Na</i>	1	\$ 60.00	\$ 60.00
4	REAR SIDE LOWER CORNER PANEL SEALANT <i>Na</i>	1	\$ 60.00	\$ 60.00
5	REAR SIDE PANEL GLASS SEALANT LH <i>Na</i>	1	\$ 80.00	\$ 80.00
6	REAR SIDE PANEL GLASS INNER SEAL LH <i>Na</i>	1	\$ 60.00	\$ 60.00

TOTAL \$ 560.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

170

TO : **LONPAC** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PC5747R**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 16.01.2023
 TIME OF ACCIDENT : 08:15 HOURS

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 1,200.00	400
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	300
3	WIRING, BULB CHECKING	\$ 250.00	30
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 650.00	60
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
6	REMOVE AND REFIX SIDE PANEL GLASS LH	\$ 200.00	60
7	REMOVE AND REFIX LINING & SEATS	\$ 480.00	x
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

850

TOTAL \$ 4,080.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,059.83
 TOTAL LABOUR COST : \$ 4,080.00
 TOTAL REPAIR COST : \$ 10,139.83

Adrian Ling.
 2/s 16/01/23.
 05 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP:8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3855.42

2/s: 3.11c ✓