



FORZA AUTOHAUS PTE LTD

39 WOODLANDS CLOSE, #01-34/35, MEGA@WOODLANDS

SINGAPORE 737856

TEL: 62781889

EMAIL: ENQUIRY@FORZAAUTO.SG

CO./GST REG: 201833292C

ESTIMATE

QUALITY TECHNOLOGY PTE LTD

Contact No. : 98867100

Code : E23010010

Date In : 16/01/2023

Vehicle No. : YQ9369S

Model : MITSUBISHI, CANTER FEB21ER3SDEN (CBU)

Chassis No. : FEB21EA35678

Parts and Labour Assessment

Description	Qty	Unit Price	Amount
Parts & Services			
FRONT BUMPER <i>Coner RHA</i>	1.00	624.30	<i>int</i> ✓ 368.40 624.30
FRONT SIGNAL LAMP RH	1.00	324.30	<i>one</i> 324.30 266
FRONT HEAD LAMP RH	1.00	628.40	<i>one</i> 628.40
FRONT DOOR RH	1.00	1,425.10	<i>Ry</i> 1,425.10
Subtotal Before Discount S\$			3,002.10
0% Discount S\$			750.51
Subtotal S\$			2,251.59
Parts & Services Total S\$			2,251.59
Labour			
TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)	1.00	120.00	<i>30</i> 120.00
TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	1.00	1,000.00	<i>300</i> 1,000.00
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	1.00	1,000.00	<i>350</i> 1,000.00 <i>680</i>
Subtotal S\$			2,120.00
Labour Total S\$			2,120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Tanjiu 97495749
'wp' 1/2/23 @ 240pm
Tanjiu @ 11h auto. on
2 days
for Resurvey after repair

947.10
680
1627.10
45813.00
2 days

Parts & Services Total S\$ 2,251.59
Labour Total S\$ 2,120.00
Grand Total S\$ 4,371.59