

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2300007
Date: 07 Jan 2023
Veh Reg No: SMM2866H
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3201177951
Reg. Date: 25/06/2019
Your Ref No: GBL6302C

Claim Type: Third Party
Accident Date: 03/01/2022

Estimate Repair Cost to Vehicle No :SMM2866H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC REAR BOOT LID	886.90	
2	2 PCS REAR BOOT LID HINGES	182.40	
3	1 PC REAR BOOT LID LOGO	66.90	
4	1 PC REAR BOOT LID "VIOS" EMBLEM	49.40	
5	1 PC REAR BOOT LID "E" EMBLEM	38.40	
6	1 PC REAR NUMBER PLATE LAMP GARNISH	188.70	
7	2 PCS REAR NUMBER PLATE LAMPS	157.60	
8	1 PC REAR BOOT LID OUTER LOCK SENSOR	148.10	
9	1 PC REAR BOOT LID RUBBER	232.90	
10	1 PC REAR BOOT LID LOCK	432.50	
11	1 PC REAR BOOT LID LOCK CHECKER	39.90	
12	1 PC REAR BOOT LID TRIM	352.00	
13	1 PC REAR BOOT LID LAMP LH	388.60	
14	1 PC REAR BOOT LID LAMP RH	388.60	
15	1 PC REAR FENDER RH	1,160.80	
16	1 PC REAR FENDER TRIM RH	356.40	
17	1 PC REAR FENDER MUDFLAP RH	78.70	
18	1 PC REAR FENDER LH	1,160.80	
19	1 PC REAR FENDER TRIM LH	356.40	
20	1 PC REAR FENDER MUDFLAP LH	78.70	
21	1 PC REAR TAIL LAMP - RH	411.80	
22	1 PC REAR TAIL LAMP PANEL RH	128.20	
23	1 PC REAR TAIL LAMP LH	411.80	
24	1 PC REAR TAIL LAMP PANEL LH	128.20	
25	1 PC REAR SPARE TYRE PANEL	855.10	
26	1 PC REAR SPARE TYRE TOP COVER	324.00	
27	1 PC REAR SPARE TYRE RH SPONGE	121.70	
28	1 PC REAR SPARE TYRE LH SPONGE	121.70	
29	1 PC REAR SPARE TYRE PANEL RH SIDE PANEL	151.70	
30	1 PC REAR SPARE TYRE PANEL LH SIDE PANEL	151.70	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2300007
Date: 07 Jan 2023
Veh Reg No: SMM2866H
Make/Model: TOYOTA VIOS 1.5E
 AUTO
Chasis No: MR2B23F3201177951
Reg. Date: 25/06/2019
Your Ref No: GBL6302C

Claim Type: Third Party
Accident Date: 03/01/2022

Estimate Repair Cost to Vehicle No :SMM2866H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
31	1 PC REAR SPARE TYRE PANEL HARDBOARD	374.60	
32	1 PC REAR PANEL	803.20	
33	1 PC REAR PANEL TRIM	301.50	
34	1 PC REAR PANEL KEYLESS SENSOR	168.80	
35	1 PC REAR BUMPER	570.90	
36	1 PC REAR BUMPER REINFORCEMENT	360.10	
37	2 PCS REAR BUMPER SIDE RETAINERS	335.80	
38	2 PCS REAR BUMPER SMALL RETAINERS	130.00	
39	1 PC REAR REFLECTOR RH	161.80	
40	1 PC REAR REFLECTOR LH	161.80	
41	1 PC REAR EXHAUST PIPE	721.40	
42	2 PCS REAR EXHAUST MOUNTING	50.20	
		13,690.70	
	Less 25%	3,422.68	10,268.11
	Special Net		
43	1 PC REAR BOOT LID "619" STICKER	30.00	
44	1 PC REAR NUMBER PLATE	50.00	
45	1 SET REAR BOOT LID TRIM CLIPS	50.00	
46	1 PC REAR FENDER STICKER RH	320.00	
47	1 SET REAR FENDER TRIM CLIPS RH	60.00	
48	1 SET REAR FENDER MUDFLAP CLIPS RH	20.00	
49	1 PC REAR FENDER STICKER LH	320.00	
50	1 SET REAR FENDER TRIM CLIPS LH	60.00	
51	1 SET REAR FENDER MUDFLAP CLIPS LH	20.00	
52	1 PC REAR SPARE TYRE FLOOR MAT	280.00	
53	1 PC REAR PANEL TRIM CLIPS	40.00	
54	1 SET REAR BUMPER STICKER	350.00	
55	2 PC REAR BUMPER "L" PLATE BRACKETS	70.00	
56	1 PC REAR BUMPER "L" PLATE	50.00	
57	1 SET REAR BUMPER CLIPS	60.00	
58	1 PC REAR WINDSCREEN SEALANT	60.00	

Kang Car Repairers Pte Ltd

I Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2300007
Date: 07 Jan 2023
Veh Reg No: SMM2866H
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3201177951
Reg. Date: 25/06/2019
Your Ref No: GBL6302C

Claim Type: Third Party
Accident Date: 03/01/2022

Estimate Repair Cost to Vehicle No :SMM2866H

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
59	1 PC REAR WINDSCREEN SEALANT RUBBER	60.00	
		1,900.00	1,900.00
	Labour		
60	1 TO CHECK WIRING	50.00	
61	1 (REAR) TO REMOVE AND REFIT WINDSCREEN GLASS	120.00	
62	1 TO REMOVE AND REFIT SEAT CUSHION	250.00	
63	1 TO REMOVE AND REFIT RH FENDER STICKER	80.00	
64	1 TO REMOVE AND REFIT LH FENDER STICKER	80.00	
65	1 TO REMOVE AND REFIT REAR BUMPER STICKER	80.00	
66	1 TO REMOVE AND REFIT REAR INNER TRIM	150.00	
67	1 TO REFIT REAR FUEL TANK	150.00	
68	1 TO REMOVE AND REFIT EXHAUST PIPE	150.00	
69	1 TO SPRAY PANEL SEALANT	150.00	
70	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	2,000.00	
71	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	3,500.00	
		6,760.00	6,760.00

Kang Car Repairers Pte Ltd

I Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2300007
Date: 07 Jan 2023
Veh Reg No: SMM2866H
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3201177951
Reg. Date: 25/06/2019
Your Ref No: GBL6302C

Claim Type: Third Party
Accident Date: 03/01/2022

Estimate Repair Cost to Vehicle No :SMM2866H

Quantity	Description	List Price	Amount
		S\$	S\$
		Total	S\$ 18,928.11
		Add GST @ 8%	1,514.25
		Total Amount Payable	<u>S\$ 20,442.36</u>

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FOUR HUNDRED FORTY TWO AND CENTS THIRTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE