

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

12-Jan-23

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1694 A

1 pc	Front n/s door protector	\$	38.00	SCR
1 pc	Rear n/s door protector	\$	38.00	SCR
1 pc	n/s rocker panel garnish	\$	290.00	DEF
1 pc	Wheel cover	\$	346.40	SCR
		\$	<u>712.40</u>	
		\$	142.48	
		\$	<u>569.92</u>	
				Less 20%
		\$	100.00	NEC
		\$	60.00	NEC
		\$	48.00	NEC
		\$	50.00	XNN
		\$	80.00	XNN
		\$	1,200.00	900
		\$	1,600.00	1,050, 1,200
		\$	150.00	50
		\$	<u>3,857.92</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental items must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

S/NETT

Check wheel alignment

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front n/s fender, front n/s door, rear n/s door, rear n/s fender, rear bumper

To putty and spray painting on the front n/s fender, front n/s door, rear n/s door, rear n/s fender, n/s rocker panel garnish, rear bumper, front n/s & o/s door protector(Silver)

To apply rustproofing on repaired panels

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

N/A LKK
31/1/2023 1730
5 Days
PIP
BEFORE PAINT PHOTOS

PARTS \$712.40
LESS 20% \$569.92
S/NETT \$208.00
LABOUR \$2,150.00
PIP Repair \$2,927.92 / 5 REPAIR DAYS