

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

12-Jan-23

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1694 A

1 pc	Front n/s door protector	\$	38.00	/scr
1 pc	Rear n/s door protector	\$	38.00	/scr
1 pc	n/s rocker panel garnish	\$	290.00	-DEF
1 pc	Wheel cover	\$	346.40	/scr
		\$	712.40	
		Less 20%	\$	142.48
			\$	569.92

S/NETT

1 set	n/s door sticker	\$	100.00	/NEC
1 pc	Rear o/s fender sticker	\$	60.00	/NEC
1 set	n/s rocker panel garnish clips	\$	48.00	/NEC
	Sundry	\$	50.00	XNN
	Check wheel alignment	\$	80.00	XNN
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front n/s fender, front n/s door, rear n/s door, rear n/s fender, rear bumper	\$	1,200.00	900
	To putty and spray painting on the front n/s fender, front n/s door, rear n/s door, rear n/s fender, n/s rocker panel garnish, rear bumper, front n/s & o/s door protector(Silver)	\$	1,600.00	1,000, 1,200
	To apply rustproofing on repaired panels	\$	150.00	50
	Total	\$	<u>3,857.92</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

N/A2 LKK
31/1/2023 1730
5 Days
PIP
BEFORE PAINT PHOTOS