

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 19 Jan 2023

**Preliminary Advice**

Vehicle No	: GBC9945A	Accident Date	: 07/01/2023
Make	: NISSAN CABSTAR	Policy No.	: SP2001163748-01
Assignment Date	: 18/01/2023	Excess	: S\$600.00
Date of Inspection	: 18/01/2023	Est. Duration of Repair	: 10
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,272.00
Revised Amount	:S\$	14,983.50
Check Items (Estimated)	:S\$	11,400.50
Total	:S\$	26,384.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	823.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,177.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Pending repair cost from repairer.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.