

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001163748-01	Date of Loss:	07/01/2023
Vehicle Reg. No.:	GBC9945A	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	MULTI WAYS EQUIPMENT PTE. LTD.	Contact No:	+6598215748
Driver:	RIPON MOHAMMED		
Make/Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Vehicle Reg. Date:	31/03/2014
Vehicle Colour:	SILVER		
Engine No:	ZD30334670K	Chassis No:	JN1SC2F24Z0855425
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	25		
Description of Accident/Loss	REFER TO POLICE REPORT		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	23,372.00
Miscellaneous Items	0.00
Labour	4,900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	28,272.00
+ GST 8.00% (S\$)	2,261.76
Nett Amount (S\$)	30,533.76

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 18 Jan 2023)

Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/GBC9945A/18/01/2023 14:24

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE <i>lt</i>	0	0.00	*25.00 FS
2	1		*FRT BUMPER <i>de</i>	0.00	0.00	*450.00 F
3	1		*FRT GRILLE ASSY <i>cm</i>	0.00	0.00	*260.00 F
4	1		*FRT GRILLE EMBLEM <i>nee</i>	0.00	0.00	*60.00 F
5	10		*FRT GRILLE CLIPS (+) <i>nee</i>	0.00	0.00	*50.00 F
6	10		*FRT GRILLE CLIPS (-) <i>nee</i>	0.00	0.00	*50.00 F
7	1		*FRT PANEL ASSY <i>lt</i>	0.00	0.00	*650.00 F
8	1		*FRT PANEL CABSTAR STICKER <i>cm</i>	0.00	0.00	*45.00 F
9	2		*FRT CORNER PANEL LH/RH <i>lt</i>	0.00	0.00	*460.00 F
10	2		*FRT UPP CORNER PANEL LH/RH <i>cm</i>	0.00	0.00	*180.00 F
11	2		*FRT UPP CORNER PROTECTOR LH/RH <i>MU</i>	0.00	0.00	*40.00 F
12	1		*FRT WIPER PANEL <i>lt</i>	0.00	0.00	*300.00 F
13	2		*FRT WIPER ARM LH/RH <i>X</i>	0.00	0.00	*140.00 F
14	2		*FRT WIPER BLADE LH/RH <i>X</i>	0.00	0.00	*30.00 F
15	1		*FRT WIPER LINGKAGE	0.00	0.00	*90.00 F
16	2		*FRT HEADLAMP LH/RH <i>lt</i>	0.00	0.00	*500.00 F
17	2		*FRT HEADLAMP LOWER APPROX LH/RH <i>lt</i>	0.00	0.00	*120.00 F
18	1		*FRT SIDE MIRROR ARM LH <i>lt</i>	0.00	0.00	*120.00 F
19	1		*FRT SIDE MIRROR RETANGULAR LH <i>cm</i>	0.00	0.00	*120.00 F
20	1		*FRT SIDE MIRROR ROUND LH <i>cm</i>	0.00	0.00	*50.00 F
21	1		*FRT SIDE MIRROR ROUND COVER LH <i>X</i>	0.00	0.00	*20.00 F
22	1		*FRT SIDE MIRROR ARM RH <i>mir</i>	0.00	0.00	*120.00 F
23	1		*FRT SIDE MIRROR RETANGULAR RH <i>mis</i>	0.00	0.00	*120.00 F
24	1		*FRT DOOR RH <i>lt</i>	0.00	0.00	*700.00 F
25	1		*FRT DOOR UPP HINGE RH <i>lt</i>	0.00	0.00	*50.00 F
26	1		*FRT DOOR LWR HINGE RH <i>lt</i>	0.00	0.00	*50.00 F
27	1		*FRT DOOR RUBBER RH <i>cm</i>	0.00	0.00	*75.00 F
28	1		*FRT DOOR LOCK RH <i>lt</i>	0.00	0.00	*120.00 F
29	1		*FRT DOOR OUTER HANDLE RH <i>X</i>	0.00	0.00	*120.00 F
30	1		*FRT DOOR INNER HANDLE RH <i>cm</i>	0.00	0.00	*35.00 F
31	1		*FRT DOOR GARNISH @FRT RH <i>mis</i>	0.00	0.00	*30.00 F
32	1		*FRT DOOR GLASS RH <i>lt</i>	0.00	0.00	*300.00 F
33	1		*FRT DOOR GLASS REGULATOR RH	0.00	0.00	*90.00 F
34	1		*FRT DOOR GLASS MOTOR RH	0.00	0.00	*280.00 F
35	1		*FRT DOOR GLASS INNER MOULDING RH <i>de</i>	0.00	0.00	*45.00 F
36	1		*FRT DOOR GLASS OUTER MOULDING RH <i>de</i>	0.00	0.00	*65.00 F
37	1		*FRT DOOR GLASS CHANNEL RH	0.00	0.00	*115.00 F
38	1		*FRT DOOR FRAME INNER TRIM RH <i>X</i>	0.00	0.00	*80.00 F
39	1		*FRT DOOR GLASS SWITCH RH <i>cm</i>	0.00	0.00	*110.00 F
40	1		*FRT DOOR SIDE SIGNAL LAMP RH <i>X</i>	0.00	0.00	*30.00 F
41	1		*FRT DOOR INNER TRIM BOARD RH <i>de</i>	0.00	0.00	*300.00 F
42	1		*FRT DOOR UPP HANDLE RH <i>de</i>	0.00	0.00	*110.00 F
43	1		*FRT STEP PANEL RH <i>cm</i>	0.00	0.00	*100.00 F
44	1		*FRT STEP GARNISH RH <i>cm</i>	0.00	0.00	*90.00 F
45	1		*FRT ROCKER PANEL RH <i>lt</i>	0.00	0.00	*430.00 F

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*FRT SCUFF PLATE RH <i>cm</i>	0.00	0.00	*60.00 F
47	1		*FRT WINDSCREEN <i>bo</i>	0.00	0.00	*550.00 F
48	1		*FRT WINDSCREEN MOULDING <i>ac</i>	0.00	0.00	*90.00 F
49	1		*FRT DASHBOARD <i>cm</i>	0.00	0.00	*1,000.00 F
50	1		*FRT DASHBOARD SUPPORT BEAM ?	0.00	0.00	*500.00 F
51	1		*FRT WASHER TANK <i>cm</i>	0.00	0.00	*80.00 F
52	1		*FRT CHASSIS CROSSMEMBER <i>bt</i>	0.00	0.00	*950.00 F
53	1		*FRT STEERING COLUMN ?	0.00	0.00	*1,000.00 F
54	1		*FRT STEERING COLUMN COVER ?	0.00	0.00	*100.00 F
55	1		*FRT STEERING COLUMN DUCT COVER ?	0.00	0.00	*100.00 F
56	1		*FRT STEERING COLUMN LOWER COVER ?	0.00	0.00	*30.00 F
57	1		*FRT STEERING GEAR ASSY ? STERING BOX	0.00	0.00	*550.00 F
58	1		*AIRCON BLOWER ?	0.00	0.00	*450.00 F
59	1		*HEATER BLOWER ?	0.00	0.00	*1,000.00 F
60	1		*FRT PILLAR INNER RH <i>bt</i> FRT PILLAR OUTER RH	0.00	0.00	*900.00 F
61	2		*FRT PILLAR INNER TRIM LH/RH <i>cm</i>	0.00	0.00	*400.00 F
62	1		*FRT ACCELERATE PEDAL ?	0.00	0.00	*100.00 F
63	1		*FRT BRAKE PEDAL ?	0.00	0.00	*100.00 F
64	1		*FRT BRAKE BOOSTER ?	0.00	0.00	*950.00 F
65	1		*FRT TYRE RH <i>X</i>	0	0.00	*280.00 FS
66	1		*FRT TYRE RIMS RH <i>X</i>	0	0.00	*180.00 FS
67	1		*FRT ABSORBER RH ?	0.00	0.00	*100.00 F
68	1		*FRT UPPER CONTROL ARM RH ?	0.00	0.00	*280.00 F
69	1		*FRT LOWER CONTROL ARM RH ?	0.00	0.00	*260.00 F
70	1		*FRT WHEEL HUB & BEARING RH ?	0.00	0.00	*450.00 F
71	1		*FRT KNUCKLE ARM RH ?	0.00	0.00	*550.00 F
72	1		*FRT SUBFRAME ?	0.00	0.00	*950.00 F
73	1		*FRT WINDSCREEN SEALANT <i>ac</i>	0	0.00	*40.00 FS
74	1		*FRT ERP BRACKET <i>ac</i>	0	0.00	*26.00 FS
75	2		*ROC STICKER <i>ac</i>	0	0.00	*40.00 FS
76	1		*FRT CABIN SUPPORT BEAM ?	0.00	0.00	*500.00 F
77	2		*FRT CABIN SUPP BRACKET LH/RH ?	0.00	0.00	*280.00 F
78	2		*FRT CABIN SUPP BUSH LH/RH ?	0.00	0.00	*80.00 F
79	1		*FRT STEERING RACK ?	0.00	0.00	*1,050.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	21,301.00
+ Margin on L,N Items 10.00% (\$\$)	2,071.00

Total Parts (\$\$)	23,372.00
--------------------	-----------

Sng Ah Tee Motor & Panel Service Pte Ltd/GBC9945A/18/01/2023 14:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

* There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO KNOCK FRT PILLAR LH,FRT DOOR LH,FRT DOOR RR PANEL LH,RR CABIN PANEL,FRT PANEL,WELD,REMOVE & REPLACE ABOVE PARTS	New	1400	1,600.00
2	TO PUTTY ,RESRPAY AND PAINTING ON AFFECTED AREAS	New	1400	1,600.00
3	TO CHECK WIRING	New		30.00
4	TO TRANSFER FRT DOOR GLASS RH	New		60.00
5	TO REMOVE & REFIX FRT WINDSCREEN	New		120.00
6	TO APPLY WHEEL ALIGNMENT	New	60	80.00
7	TO STRAIGHTEN FRT CHASSIS	New	250	350.00
8	TO REMOVE & REFIX FRT DASHBOARD	New	150	180.00
9	TO REMOVE & REFIX FRT UNDERCARRIAGE	New	200	250.00
10	TO LIFT UP FRT CABIN photo	New	250	350.00
11	TO TOP UP AIRCON GAS	New	?	100.00
12	TO DIAGNOSE AND RESET FAULT CODE	New	100	180.00

Gross Labour Cost (S\$)

4,900.00

Sng Ah Tee Motor & Panel Service Pte Ltd/GBC9945A/18/01/2023 14:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rahul

Hp 90010068

10

L/S

18/01/23 @ 1600

EXCESS: 600

Revert

Resurvey after repair