



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 34T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET NUMBER PLATE WITH HOUSING.NETT (SN)	BENT	60.00	60.00
1	FRONT BUMPER (SN)	DEFORMED	1,522.98	1,522.98
2	LOCK CLIP @\$3.05 (SN)	NECESSARY	6.10	6.10
1	FRONT BUMPER MB EMBLEM (SN)	NECESSARY	68.61	68.61
1	LICENSE PLATE MOLDING (SN)	DEFORMED	121.89	121.89
1	IMPACT ABSORBER (SN)	NOT NECESSARY	163.35	-
1	TOP BASIC MOUNTING FOR BUMPER (SN)	NECESSARY	184.40	184.40
1	MERCEDES STAR (SN)	CRACKED	145.89	145.89
1	MERCEDES STAR CARRIER (SN)	NOT NECESSARY	82.12	-
1	SILVER GRILLE MOLDING (SN)	DEFORMED	238.43	238.43
1	LH/TOP ORNAMENTAL TRIM (SN)	NECESSARY	86.07	86.07
1	RH/TOP ORNAMENTAL TRIM (SN)	NECESSARY	82.30	82.30
1	LH/BOTTOM ORNAMENTAL TRIM (SN)	NECESSARY	82.30	82.30
1	RH/BOTTOM ORNAMENTAL TRIM (SN)	NECESSARY	82.30	82.30
1	GRILLE (SN)	NOT NECESSARY	194.14	-
1	RH/HEADLAMP UNIT (SN)	NOT NECESSARY	3,066.01	-
			6,186.89	2,681.27
	<u>LABOUR</u>			
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.		1,920.00	960.00
	RESPRAY FRONT BUMPER & ENGINE HOOD.		1,800.00	1,600.00
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT.		380.00	380.00
	TO REMOVE,REPLACE HEADLAMP WITH FOCUS. NETT.		120.00	120.00
	INITIAL ACCIDENT DIAGNOSIS PERFORM CHECK KNOCKING NOSIE.	NOT NECESSARY	960.00	-
			5,180.00	3,060.00
GRAND TOTAL			11,366.89	5,741.27

Report Ref No. CS/FCI23000602/Twy3m4



RECOMMENDED COST OF REPAIRS			5,741.27
-----------------------------	--	--	----------

Report Ref No. CS/FCI23000602/Twy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.