



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI23000602/Twy3m4

Date: 27/04/2023

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 1945G	Veh. Inspected	SMA 34T
Policy No.		Coverage (\$)	0.00
Claim No.	D23000246MFCV	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	18/01/2023

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ B180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDD2462422J475786	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	CONTINENTAL	6 mm
L/H Front Tyre	205/55R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/55R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/55R16	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/01/2023	Inspection Date	02/03/2023
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------