

ASS RECDY.

REF:

CS/FC123000602/7ny3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$92K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 1.8.1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5MA34T Yr Regn: 208, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz B180 C.C. 1595

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NDD2462422 J435786

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: NIL / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 2/3/23

Survey held at: CSC Pandan Imp.

Des. of Damages: Frt / Rear / O/S / N/S / W/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/04/2023 Finalise P/P \$5,741.27 @ 5 days before GST (Red \$5,625.62/49%)

Date/Time, File Pass to?

27/04/2023
1) Typist

Date/Time, File Return to?

2) _____

Report Format: TP

Lump Sum / I.B.I. (P/P \$5,741.27)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 85001111-X

ESTIMATE FOR SMA34T

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

62466
SMA34T / 21/05/2018
/ 0
WDD2462422J475786
27091031611671
MB/B 180 SEDAN (W246) "STYLE
026 650 Calcit Whit/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator				
WF001862	Credit	02/03/2023/ 10:31		371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : DMPSCSNW00104742201 // 17-1-2023								
DRIVE IN/TP VEH NUMBER : 17-1-2023 // YQ1945G -								
DATE IN/DATE SURVEY:								
DIRECT SETTLEMENT BY:								
A BPILAB								960 1920.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES								1600 1800.00
RESPRAY FRONT BUMPER & ENGINE HOOD								
A BPILAB							0.10	✓ 380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								
A BPILAB								✓ ? 120.00
TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT								
S BPNSUB								bt ✓ 60.00
SUPPLY 1 SET NUMBER PLATE WITH HOUSING. NETT								
A 60102301								nn x 960.00
INITIAL ACCIDENT DIAGNOSIS PERFORM CHECK KNOCKING NOSIE								
M FRONT BUMPER					1.00	1522.98	00.00	de ✓ 1522.98
M LOCK CLIP					2.00	3.05	00.00	ne ✓ 6.10
M FRONT BUMPER MB EMBLEM					1.00	68.61	00.00	ne ✓ 68.61
M LICENSE PLATE MOLDING					1.00	121.89	00.00	de ✓ 121.89
M IMPACT ABSORBER					1.00	163.35	00.00	nn x ? 163.35
M TOP BASIC MOUNTING FOR BUMPER					1.00	184.40	00.00	ne ✓ ? 184.40
M MERCEDES STAR					1.00	145.89	00.00	nn ✓ 145.89
M MERCEDES STAR CARRIER					1.00	82.12	00.00	nn x ? 82.12
M SILVER GRILLE MOLDING					1.00	238.43	00.00	de ✓ 238.43
M LH/TOP ORNAMENTAL TRIM					1.00	86.07	00.00	ne ✓ 86.07
M RH/TOP ORNAMENTAL TRIM					1.00	82.30	00.00	ne ✓ 82.30
M LH/BOTTOM ORNAMENTAL TRIM					1.00	82.30	00.00	ne ✓ 82.30
M RH/BOTTOM ORNAMENTAL TRIM					1.00	82.30	00.00	ne ✓ 82.30

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111 X

ESTIMATE FOR SMA34T

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

62466
SMA34T / 21/05/2018
/ 0
WDD2462422J475786
27091031611671
MB/B 180 SEDAN (W246) "STYLE
026 650 Calcit Whit/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator	
WF001862	Credit	02/03/2023/ 10:31		371 / Go Chee Han	
Description of Goods / Services					
					Qty
					Unit Price
					Disc%
					Amount
M	GRILLE				1.00
					194.14
					00.00
					194.14 MY
M	RH/HEADLAMP UNIT				1.00
					3066.01
					00.00
					3066.01 MY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification's to be allowed
- Supplementary items, must be resurveyed and is subject to final approval from insurance Company

Agreed with the Repairer

etc

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

8% GST on **Nett 11,366.89**
909.35

Authorized signatory and company stamp

Total Payable 12,276.24

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMA34T

Finalization

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No	62466
Reg No/Reg Date	SMA34T / 21/05/2018
Date In/Mileage	02/03/2023/ 89482
Chassis No	WDD2462422J475786
Engine No	27091031611671
Make/Model	MB/B 180 SEDAN (W246) "STYLE
Colour/Trim	026 650 Calcit Whit/ 041 111 Black

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WF001862	Credit	21/03/2023/ 19:49	CH	371 / Go Chee Han					
Z REQUEST									
Customer Request									
TO REPLACE BOTH NUMBER PLATE									
HOUSING									
M BPNSUN									
POLICY NO/ACC DATE : DMPSCSNW00104742201 // 17-1-2023									
DRIVE IN/TP VEH NUMBER : 17-1-2023 // YQ1945G - MS FIRST CAPITAL									
DATE IN/DATE SURVEY: 2-3-2023 // TAUFIK - LKK									
DIRECT SETTLEMENT BY: 23-2-2023 // RACHEL WU - MS FIRST CAPITAL									
A BPILAB									960.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								0.05	1600.00
A BPIRES								0.10	380.00
RESPRAY FRONT BUMPER & ENGINE HOOD									
A BPILAB									
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO									
IDENTIFICATION STANDARD. NETT									120.00
A BPILAB									
TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT									60.00
S BPNSUB									
SUPPLY 1 ONE PC NO PLATE									
X FRONT BUMPER						1.00	1522.98	00.00	1522.98
X LOCK CLIP						2.00	3.05	00.00	6.10
X FRONT BUMPER MB EMBLEM						1.00	68.61	00.00	68.61
X LICENSE PLATE MOLDING						1.00	121.89	00.00	121.89
X TOP BASIC MOUNTING FOR BUMPER						1.00	184.40	00.00	184.40
X MERCEDES STAR						1.00	145.89	00.00	145.89
V SILVER GRILLE MOLDING						1.00	238.43	00.00	238.43
X LH/TOP ORNAMENTAL TRIM						1.00	86.07	00.00	86.07
X RH/TOP ORNAMENTAL TRIM						1.00	82.30	00.00	82.30
X LH/BOTTOM ORNAMENTAL TRIM						1.00	82.30	00.00	82.30
X RH/BOTTOM ORNAMENTAL TRIM						1.00	82.30	00.00	82.30

Confirmed & accepted by

8% GST on **Nett** 5,741.27
459.30

Total Payable 6,200.57

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG