

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000611/RNP3Q2**Date:** 18/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNA00004932201		
Claimant Vehicle No :	SLS6182B	Insured Vehicle No :	PC6569G		
Date of Loss:	13/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200394/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS6182B		
Make & Model:	TOYOTA SIENTA, 1.5 CVT STD (A)	Engine No:	2NRX216523
Reg. Date:	28/09/2017 (Man. Year: 2017)	Chassis No:	MHFZ28H3900041908
Colour:	Grey	Odometer:	129186 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,785.25	1,278.75	1,506.50	54.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,020.00	680.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,485.25	2,298.75	2,186.50	48.75
+ GST 8.00/8.00% (S\$)	358.82	183.90	174.92	48.75
Nett Amount (S\$)	4,844.07	2,482.65	2,361.42	48.75

INSPECTION

Date of Assignment:	18/01/2023		
Date Inspected:	23/02/2023 Inspected At:		Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2023)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 CVT STD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS6182B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	455.00 FL	*- FL
2	1		*REAR BUMPER LOWER CTR GARNISH	Deformed	178.00 FL	*178.00 FL
3	1		*REAR BUMPER TOW COVER LH	Not Necessary	32.00 FL	*- FL
4	10		*REAR BUMPER CLIPS	Not Necessary	55.00 FL	*- FL
5	1		*REAR FOGLAMP ASSY	Not Necessary	195.00 FL	*- FL
6	1		*REAR FOGLAMP BRACKET	Not Necessary	55.00 FL	*- FL
7	1		*REAR BOOTLID	Bent	1,100.00 FL	*1,100.00 FL
8	1		*REAR BOOT CENTER TRIM	Not Necessary	270.00 FL	*- FL
9	1		*REAR BOOT EMBLEM	Necessary	58.00 FL	*58.00 FL
10	1		*REAR BOOT SIENTA STICKER	Necessary	59.00 FL	*59.00 FL
11	1		*REAR BOOT G STICKER	Necessary	55.00 FL	*55.00 FL
12	1		*REAR WINDSCREEN MOULDING	Necessary	715.00 FL	*215.00 FL
13	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*30.00 FS
14	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
15	1		*REAR REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
					Sub Total (\$\$)	
					3,592.00	1,695.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	
					806.75	416.25
					Total Parts (\$\$)	
					2,785.25	1,278.75

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK ,WELD ,REMOVE & REPLACE ABOVE PARTS	New	600.00	400.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	750.00	400.00
3	TO CHECK WIRING	New	30.00	0.00
4	TO REMOVE AND REFIX RR WINDSCREEN	New	120.00	120.00
5	TO DIAGNOSE & RESET FAULT CODE	New	120.00	60.00
6	TO REMOVE & REFIX REAR TRIMS	New	80.00	40.00
Gross Labour Cost (S\$)			1,700.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >