

S. REC BY: TEWA

REF: CS/C1/23000614/Typs

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated cost: \_\_\_\_\_

OD /  TP /  VS /  TP RES /  OD RES /  EVA /  INV /  MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. DMPCSNW00260962202

Claims No. SNM23D200165/C01/CHEESC

Sum Insured: \_\_\_\_\_ Excess: RM 2500

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	
N/S	O/S

Bal. or Market Value: \$340K.

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA /  REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMW3828J Yr Regn: 2020, Nov

Type:  M. Car /  M. Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Posche Cayenne E3 C.D. 2995

Colour: White A/C:  Insured /  Std /  NI /  NA

Sp. Reading: 38691 T/Radio:  Insured /  Std /  NI /  NA

Eng/No: \_\_\_\_\_

C/No: WPI 222942 LPA 06712

Gen. Cond:  Good /  Fair /  Poor /  Burnt

Steering:  In order /  Jammed /  Leaked /  Burnt or

Brake:  In order /  Jammed /  Leaked /  Burnt or

Modi:  Nil /  S/Rim /  STD A/Rim or

Tyre Size: F: 255/55R19

R: 275/50R19

BS /  DUN /  EXNOVA /  GY /  FBS /  LIZA /  MID /  DHTSU /  PIR /  SUMI /

TOYO / YOKO, or \_\_\_\_\_

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 6/1/2023 D.O.I. 20/1/23.

Survey held at Eurocars

Des. of Damages:  Front /  Rear /  O/S /  N/S /  U/C /  Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
7/7/23	Final fig \$33,407.60 confirmed by email (Red 34,946.60, 51%)

Date/Time, File Pass to?  : Prel. Report  : Final Report

Days Of Repair: 6

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to? 2) 7/7/23-typist

Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Invs (\$)  : Weekend (\$)

Survey Fee:	_____
Transportation:	_____
S + RS	SI
Photos	_____
Others	_____

Report Format: Merimen  
Lump Sum / I.B.R. / \$33,407.60

Name & Address:  
**Motor Claims Department**  
**CHINA TAIPING INSURANCE P/L**  
 3 ANSON ROAD  
 #16-00 SPRINGLEAF TOWER  
 SINGAPORE 079909

Vehicle No:  
**SMW3828J**  
 Brand & Model:  
 Cayenne  
 Chassis/VIN No:  
**WP1ZZZ9YZLDA06712**  
 WIP#: **41297**

Date:  
 16-Jan-23  
 Franchise:  
 PORSCHE  
 Contact Person (Eurokars):  
 LIM  
 Contact No (Eurokars):  
 6331 0685

Email/Fax No: \_\_\_\_\_ Contact No: \_\_\_\_\_  
 Type of Claim: \_\_\_\_\_ YEAR MODEL: \_\_\_\_\_  
 OWN DAMAGE 18/11/2020

### PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER	P9Y0-807-217- -G2X	1	de ✓	-	\$ 2,531.20
2	TOWING COVER LH	P9Y0-807-155- -G2X	1	cut ✓	-	\$ 112.60
3	TOWING COVER RH	P9Y0-807-156- -G2X	1	mis ✓	-	\$ 112.60
4	EXPANDER NUT	PWHT-004-935- -	4	na ✓	-	\$ 6.80
5	CLAMP	P9Y0-423-337- -	4	na ✓	-	\$ 20.00
6	RIVET	PN -038-501-2 -	8	na ✓	-	\$ 15.20
7	DISC LH UPPER	P9Y0-807-685- -OK1	1	?	-	\$ 165.20
8	DISC RH UPPER	P9Y0-807-686- -OK1	1	?	-	\$ 165.20
9	DISC TRIM LH CENTER	P9Y0-807-877- -OK1	1	?	-	\$ 115.00
10	DISC TRIM RH CENTER	P9Y0-807-878- -OK1	1	?	-	\$ 115.00
11	DISC TRIM LH LOWER	P9Y0-807-973- -OK1	1	?	-	\$ 108.50
12	DISC TRIM RH LOWER	P9Y0-807-974- -OK1	1	?	-	\$ 108.50
13	TRIM SILVER LH CENTER	P9Y0-807-245- -M7U	1	?	-	\$ 139.80
14	TRIM SILVER RH CENTER	P9Y0-807-246- -M7U	1	?	-	\$ 139.80
15	TRIM RHODIUM SILVER LH	P9Y0-807-245-A -M7U	1	?	-	\$ 139.80
16	TRIM RHODIUM SILVER RH	P9Y0-807-246-A -M7U	1	?	-	\$ 139.80
17	TRIM SILVER CENTER UPPER	P9Y0-807-179- -M7U	1	em ✓	-	\$ 144.10
18	TRIM SILVER CENTER	P9Y0-807-179-A -M7U	1	de ✓	-	\$ 144.10
19	TRIM SILVER CENTER LOWER	P9Y0-807-179-B -M7U	1	de ✓	-	\$ 144.10
20	FRONT BUMPER LOWER SPOILER	P9Y0-807-061- -OK1	1	de ✓	-	\$ 1,072.60
21	COVER BRUSHED STAINLESS STEEL	P9Y0-807-833- -6M7	1	X	-	\$ 1,211.30
22	GRILLE LOWER CENTER	P9Y0-807-684- -OK1	1	de ✓	-	\$ 190.10
23	LICENSE PLATE BRACKET	P9Y0-807-287- -OK1	1	cut ✓	-	\$ 135.20
24	EXPANSION RIVET	PPAF-038-549- -	4	na ✓	-	\$ 2.80
25	FRONT BUMPER GRILLE CENTER	P9Y0-807-683-P -OK1	1	cut ✓	-	\$ 364.60
26	GRILLE LH	P9Y0-807-681- -OK1	1	?	-	\$ 199.50
27	GRILLE RH	P9Y0-807-682- -OK1	1	?	-	\$ 199.50
28	GRILLE LH LOWER	P9Y0-807-675- -OK1	1	de ✓	-	\$ 140.80
29	GRILLE RH LOWER	P9Y0-807-676- -OK1	1	de ✓	-	\$ 140.80
30	GUIDE LH	P9Y0-807-177-C -	1	de ✓	-	\$ 100.80
31	GUIDE RH	P9Y0-807-178-C -	1	?	-	\$ 100.80
32	EXPANDER NUT	PWHT-004-935- -	6	na ✓	-	\$ 10.20
33	BLIND RIVET	PN -903-463-01-	10	na ✓	-	\$ 18.00

34	AIR GUIDE BUMPER LH	P9Y0-807-957-C -OK1	1	?	-	\$ 79.30
35	AIR GUIDE BUMPER RH	P9Y0-807-958-C -OK1	1	?	-	\$ 79.30
36	AIR GUIDE BUMPER LOWER LH	P9Y0-807-959- -OK1	1	?	-	\$ 57.80
37	AIR GUIDE BUMPER LOWER RH	P9Y0-807-960- -OK1	1	?	-	\$ 57.80
38	FOAM PART LH	P9Y0-807-665- -	1	?	-	\$ 100.00
39	FOAM PART RH	P9Y0-807-666- -	1	?	-	\$ 100.00
40	SENSOR GASKET	P5Q0-919-133- -9B9	6	nei	-	\$ 20.40
41	SENSOR OUTER	P5Q0-919-275-C -G2X	2	X	-	\$ 560.40
42	RETAINER FOR ULTRASOUND SENSOR LH OUTER	P9Y0-807-129- -	1	nei	-	\$ 42.90
43	RETAINER FOR ULTRASOUND SENSOR RH OUTER	P9Y0-807-130- -	1	nei	-	\$ 42.90
44	SENSOR CENTER	P5Q0-919-275-B -G2X	2	nei	-	\$ 560.40
45	RETAINER FOR ULTRASOUND SENSOR LH CENTER	P9Y0-807-131- -	1	nei	-	\$ 42.90
46	RETAINER FOR ULTRASOUND SENSOR RH OUTER	P9Y0-807-132- -	1	nei	-	\$ 42.90
47	HEADLIGHT BRACKET LH	P9Y0-807-571-B -	1	?	-	\$ 80.60
48	HEADLIGHT BRACKET RH	P9Y0-807-572-B -	1	?	-	\$ 80.60
49	BUMPER RETAINER LH	P9Y0-807-049-F -	1	?	-	\$ 87.40
50	BUMPER RETAINER RH	P9Y0-807-050-F -	1	?	-	\$ 87.40
51	CARRIER BRACKET UPPER	P9Y0-805-015-C -	1	?	-	\$ 573.20
52	CROSS MEMBER UPPER	P9Y0-805-241-B -	1	?	-	\$ 177.70
53	AIR DUCT FRONT CENTER UPPER	P9Y0-129-251-D -	1	?	-	\$ 146.40
54	AIR DUCT REAR CENTER UPPER	P9Y0-121-673- -	1	?	-	\$ 185.30
55	AIR GUIDE REAR CENTER	P9Y0-121-707-B -	1	?	-	\$ 149.40
56	AIR FLAP LH	P9Y0-121-699-C -OK1	1	?	-	\$ 129.20
57	AIR FLAP RH	P9Y0-121-700- -OK1	1	?	-	\$ 129.20
58	AIR DUCT CENTER LOWER FRONT	P9Y0-121-710- -OK1	1	?	-	\$ 133.00
59	AIR DUCT CENTER LOWER REAR	P9Y0-121-293- -	1	?	-	\$ 147.10
60	AIR FLAP VANES CENTER	P9Y0-805-519-F -OK1	1	?	-	\$ 745.00
61	AIR FLAP VANES LOWER CENTER	P9Y0-121-451-H -OK1	1	?	-	\$ 305.70
62	AIR DUCT FOR INTERCOOLER LH	P9Y0-117-335-AC-OK1	1	?	-	\$ 223.60
63	AIR DUCT FOR INTERCOOLER RH	P9Y0-117-336-AC-OK1	1	?	-	\$ 223.60
64	AIR FLAP VANES INTERCOOLER LH	P9Y0-122-355-E -OK1	1	?	-	\$ 262.90
65	AIR FLAP VANES INTERCOOLER RH	P9Y0-122-356-C -OK1	1	?	-	\$ 262.90
66	FRONT SUPPORT PANEL	P9Y0-805-594-R -	1	?	-	\$ 917.10
67	SLIDE RAIL LH	PPAB-806-185- -	1	?	-	\$ 59.20
68	SLIDE RAIL RH	PPAB-806-186- -	1	?	-	\$ 59.20
69	SUPPORT BRACKET FOR RAIL LH	PPAB-801-677-00-	1	?	-	\$ 51.60
70	SUPPORT BRACKET FOR RAIL RH	PPAB-801-678-00-	1	?	-	\$ 51.60
71	FRONT BUMPER REINFORCEMENT	P9Y0-807-109-B -	1	?	-	\$ 1,368.10
72	BLIND RIVET NUT	PN -908-173-02-	8	?	-	\$ 22.40
73	SUPPORT FOR BUMPER LH	P9Y0-807-711-C -	1	?	-	\$ 56.40
74	SUPPORT FOR BUMPER RH	P9Y0-807-712-C -	1	?	-	\$ 56.40
75	FRON BUMPER SPONGE	P9Y0-807-550-F -	1	?	-	\$ 75.80
76	BRACKET FOR FRONT SUPPORT PANEL LH	P9Y0-805-515-C -	1	?	-	\$ 102.70
77	BRACKET FOR FRONT SUPPORT PANEL RH	P9Y0-805-516-C -	1	?	-	\$ 102.70
78	BRACE FOR SUPPORT PANEL LH	P9Y0-805-527-C -	1	?	-	\$ 67.00

## REPAIR ESTIMATE

79	BRACE FOR SUPPORT PANEL RH	P9Y0-805-528-C -	1	?	-	\$	67.00
80	SIDE MEMBER LH	PPAB-802-037- -	1	?	-	\$	373.40
81	SIDE MEMBER RH	PPAB-802-038-A -	1	?	-	\$	373.40
82	REINFORCEMENT LH	PPAB-802-441- -	1	?	-	\$	297.70
83	REINFORCEMENT RH	PPAB-802-442- -	1	?	-	\$	297.70
84	SUPPORT LH	PPAB-803-329- -	1	?	-	\$	190.70
85	SUPPORT RH	PPAB-803-330- -	1	?	-	\$	194.50
86	BRACKET LH	PPAB-805-201- -	1	?	-	\$	55.70
87	BRACKET RH	PPAB-805-202- -	1	?	-	\$	55.70
88	BRACKET	P9Y0-805-137- -	1	?	-	\$	39.50
89	LOCK CARRIER FOR RADIATOR MOUNTING	PPAB-805-295- -	1	?	-	\$	983.60
90	BRACKET	PPAB-805-371- -	2	?	-	\$	55.20
91	BONNET	P9Y0-823-031-DY-GRV	1	?	-	\$	4,173.10
92	HINGE LH	P9Y0-823-301-E -	1	X	-	\$	122.10
93	HINGE RH	P9Y0-823-302-E -	1	X	-	\$	122.10
94	BONNET DAMPER	P9Y0-823-359-A -	1	X	-	\$	49.60
95	COVER FOR HINGE LH	P9Y0-823-187-B -	1	?	-	\$	24.30
96	COVER FOR HINGE RH	P9Y0-823-188-B -	1	?	-	\$	24.30
97	CATCH BRACKET LH	P9Y0-823-185-A -	1	?	-	\$	91.30
98	CATCH BRACKET RH	P9Y0-823-186-A -	1	?	-	\$	91.30
99	CAP NUT	PWHT-001-308- -	4	?	-	\$	14.40
100	LID LOCK	P9Y0-823-509-A -	2	?	-	\$	544.80
101	GASKET SEAL FOR WATER BOX	P958-823-723-00-	1	?	-	\$	104.40
102	ACTUATING LEVER	P9Y0-823-661-D -	1	?	-	\$	45.30
103	BONNET INSULATOR	P9Y0-863-831-B -	1	?	-	\$	275.70
104	INSULATOR CLIPS	P1T0-863-727- -	12	?	-	\$	12.00
105	SUPPORT PANEL TOP COVER	P9Y0-805-504-F -OK1	1	?	-	\$	217.00
106	CLIP	P958-008-540-00-	4	?	-	\$	21.20
107	FENDER UPPER COVER LH	P9Y0-806-441-F -OK1	1	?	-	\$	170.10
108	FENDER UPPER COVER RH	P9Y0-806-442-F -OK1	1	?	-	\$	170.10
109	CLIPS	P958-805-163-00-	6	?	-	\$	31.20
110	EXPANSION RIVET	PPAF-004-750- -	4	?	-	\$	11.60
111	LED HEADLIGHTS LH	P9Y0-941-039-R -	1	?	-	\$	4,097.50
112	LED HEADLIGHT RH	P9Y0-941-040-AA-	1	?	-	\$	4,097.50
113	GASKET LH	P9Y0-941-119-A -	1	?	-	\$	191.60
114	GASKET RH	P9Y0-941-120-A -	1	?	-	\$	191.60
115	PROTECTIVE CAP LH	P9Y0-941-607-B -	1	?	-	\$	66.10
116	PROTECTIVE CAP RH	P9Y0-941-608-B -	1	?	-	\$	66.10
117	FAN FOR HEADLAMPS	P9Y0-941-052-A -	2	?	-	\$	729.40
118	ADDITIONAL HEADLAMP LH	P9Y0-941-181-B -	1	X	-	\$	827.70
119	ADDITIONAL HEADLAMP RH	P9Y0-941-182-B -	1	X	-	\$	827.70
120	PORSCHE CREST	P9P1-853-601- -	1	al	-	\$	292.00
121	DESK PAD CREST	P9P1-853-611- -	1	al	-	\$	18.60
122	HOOD BADGE NUT	PWHT-004-974- -	2	al	-	\$	4.00
123	CAMERA	P958-980-546-00-	1	?	-	\$	714.90

124	TRIM PANEL FOR CAMERA	P9Y0-807-644- -OK1	1	ant	-	\$	147.20
125	BRACKET FOR CAMERA	P9Y0-807-997- -	1	dis	-	\$	48.40
126	RADIATOR	P958-121-251-10-	1	?	-	\$	1,450.20
127	CAP	P9A7-133-335-00-	1	?	-	\$	31.50
128	FAN HOUSING	PPAB-121-207-30-	1	?	-	\$	683.00
129	RADIATOR FAN WITH CONTROL LH	PPAB-959-455- -	1	?	-	\$	2,821.60
130	RADIATOR FAN WITH CONTROL RH	PPAB-959-455-A -	1	?	-	\$	2,821.60
131	P000-043-301-12-/ANTIFREEZE PROTECTION	P000-043-305-15-	6	?	-	\$	235.20
132	A/C CONDENSER WITH DRYER	PPAB-816-421-D -	1	?	-	\$	2,344.40
133	(WB35) WARNING SIGN	P7PP-010-006-A -	1	?	-	\$	6.60
134	(WE72) START/STOP WARNING SIGNSTICKER	P7PP-010-786-T -	1	?	-	\$	72.60
135						\$	-

Sub-Total (Parts Price) \$ - \$ 49,448.70

**LABOUR / SERVICES CHARGES**

NO	DESCRIPTION		REVISED	PRICE
1	TO REMOVE /REPLACE BONNET, FRT BUMPER, REINFORCEMENT, FRONT SUPPORT PANEL & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560.	3900	\$ 10,920.00
2	TO RESPRAY BONNET, FRT BUMPER	1	2400	\$ 2,600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.		150	\$ 250.00
4	TO SUPPLY FRONT LICENCE PLATE WITH CASING	ant ✓	nett	\$ 70.00
5	TO SUPPLY 1 PC CHASSIS STICKER ON BONNET	net -	nett	\$ 150.00
6	TO REMOVE & REPLACE TURBO COOLER, RADIATOR, CONDENSER AND RADIATOR FAN ASSY.	?	nett	\$ 1,560.00
7	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	?	nett	\$ 500.00
8	TO TRANSFER THE FRONT BUMPER SENSORS.	150		\$ 300.00
9	TO TRANSFER THE FRONT CAMERA.	✓	nett	\$ 400.00
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150		\$ 250.00
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	✓	nett	\$ 600.00
12	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	X	nett	\$ 300.00
13	SUNDRIES.	20	nett	\$ 50.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Surveyor Remarks:

Sub-Total (Labour Price) \$ - \$ 17,950.00

Parts Price \$ **REVISED** - \$ **PRICE** 49,448.70

**REPAIR ESTIMATE**

Labour Price	\$	-	\$	17,950.00
Total (Initial Estimate)	\$	-	\$	67,398.70
Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	-	\$	67,398.70
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	-	\$	67,398.70
GST	8%	\$	-	\$ 5,391.90
<b>GRAND TOTAL</b>	\$	-	\$	<b>72,790.60</b>

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Taufik 97415749 / 62563561  
 Not Authorise Ex: t69  
 20/1/23 2915  
 05 days  
 taufik@khauto.com  
 Resurvey before paint.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: