

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 26 Jan 2023

Preliminary Advice

Vehicle No	: SMW3828J	Accident Date	: 06/01/2023
Make	: PORSCHE CAYENNE	Policy No.	: DMPCSNW00260962202
Assignment Date	: 18/01/2023	Excess	: S\$2,500.00
Date of Inspection	: 20/01/2023	Est. Duration of Repair	: 5
Inspection At	: TRANS EUROKARS PTE LTD - TANJONG PENJURU (HQ) 27A TANJONG PENJURU SINGAPORE 609042		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	67,398.70
Revised Amount	:S\$	18,731.50
Check Items (Estimated)	:S\$	37,095.90
Total	:S\$	55,827.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	340,000.00
COE / PARF Rebate	:S\$	123,955.00
Salvage Value	:S\$	
Margin for Repair	:S\$	216,045.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.