

SMT 7742P.

Hui Rong

Subaru XV

TPAXA.

JFIGT7KLSKG061258

Rear Bumper	Distorted	679.50 ✓
Rear Bumper Lips	Neu	30(SN) ✓
Rear Bumper Side Holder x 02	Dmg	$38.4 \times 2 = 76.80$ ✓
Rear Bumper Tow Cover.	Missing	30.40 ✓
Rear Bumper Reinforcement.	Bent	388.50 ✓
Rear Bumper Side Reflector x 02	Lt at	145.8 $145.8 \times 2 = 291.60$ ✓
Reverse Sensor	Dmg	280(SN) 485.6 280(SN) ✓
Rear End Panel	Dented	485.60 ✓
Rear End Panel Top Garnish.	Dented	181.8 181.80 ✓
Rear End Panel Top Garnish Clips	Neu	20(SN) ✓
Rear End Panel Top Garnish Sealant.	Neu	60(SN) ✓
Taillamp x 02.	Lt crushed	425.20 $425.2 \times 2 = 850.40$ ✓
Tailgate	Dented	1202.4 1202.40 ✓
Tailgate Lock	Dmg	276.40 ✓ 276.4

SMT 7742P.

Tailgate Weatherstripe.	cut	156.70 ✓
Tailgate Reflector x 02	HP nu	302.10 x 2 = 604.20 X
Tailgate Glass Moulding.	} per	149.40 ✓
Tailgate Glass Sealant.		60 (SN) ✓
Subaru Wording.	} per	62.9 ✓
AWD Wording.		60.5 ✓
XV Wording.		59.4 ✓
Emblem.		58.9 ✓
	HP nu	
Spore Tyre Panel Top Board.		665.80 X.

444060 S.N: 370
355248

SMJ 7742P

Panel Beating	1200 900
Spray Painting	1200 950
Wiring.	50 30
To remove reverse sensor	100 50
To remove rear camera.	100 50
To remove upholstery. 2320	150 60
To remove tailgate gl(s)	180 120
To transfer tailgate fittings.	150 80
To apply buff coat.	150 80.

total: 6242.48

L/S : SK.

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SLC.