



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: HO WINNIE			Ref: CS/ASM23000616/Aqp3m4 Date: 06/03/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SBG 444S	Veh. Inspected	SMJ 7742P	
Policy No.	GA365643	Coverage (\$)	0.00	
Claim No.	S3M04I3I	Excess (\$)	0.00	
Assign From	HO WINNIE	Assign Date	18/01/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUBARU XV	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JF1GT7KL5KG061258	Colour	BLUE	
Odometer	80902 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/01/2023	Inspection Date	19/01/2023	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	