# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01

Singapore 068897

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Chan Kian Chuan 15 Feb 2023 Date:

# **Preliminary Advice**

Insured Vehicle No : SGC18B

: 14/01/2023 TP Vehicle No : SLS1627T **Accident Date** Make : TOYOTA C-HR Assignment Date : 18/01/2023

Date of Inspection : 14/02/2023 Est. Duration of Repair

Inspection At : LIAN HER MOTORS (ANG MO KIO)

BLK 5038, ANG MO KIO INDUSTRIAL PARK 2, #01-405

SINGAPORE 569541

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,098.02
Revised Amount	:S\$	1,467.33
Check Items (Estimated)	:S\$	362.40
Total	:S\$	1,829.73

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject ( X ) to consistency check, part prices and labour cost.