



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TPVehicle No. : GBB9044EMake & Model : FIAT DOBLO 1.3Year of Manufacture : 2010Chassis No. : ZFA22300005727106Ins Company : AUTO & GENERAL

Engine No. : \_\_\_\_\_

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 21.12.2022Time of Accident : 1020

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor

**Repair Estimates**

Case Owner : \_\_\_\_\_

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 2,135.50

Contact No

Plus/Less 10% \$ 213.55**Frt Counter Operation**

63837103 – Patrick Tia

Total of Cost / List \$ 2,349.05[PatrickTia@sparkcarcare.com](mailto:PatrickTia@sparkcarcare.com)(b) Nett Price Items \$ -

63837730 - Brenda Ng

Less \_\_\_\_\_

[BrendaNg@sparkcarcare.com](mailto:BrendaNg@sparkcarcare.com)

Total of Nett Item \_\_\_\_\_

63837466 – Rohani

(c) Special Nett Items \$ 610.00[RohaniM@sparkcarcare.com](mailto:RohaniM@sparkcarcare.com)Total Parts Cost (Appendix A) \$ 2,959.05**Workshop Operation**

63837656 - Ngo Toh Wee

Labour (Appendix B) \$ 1,580.00[Ngotw@sparkcarcare.com](mailto:Ngotw@sparkcarcare.com)

63838115 -

Total Repair Cost \$ 4,539.05

63837362 -

The above total will be subjected to 7% G.S.T.

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

|              |   |                   |                  |   |        |
|--------------|---|-------------------|------------------|---|--------|
| Vehicle No   | : | GBB9044E          | Case Owner       | : | JOHARI |
| Make & Model | : | FIAT DOBLO 1.3    | Year Manufacture | : |        |
| Chassis No   | : | ZFA22300005727106 | Engine No        | : | 0      |
| Sales Order  | : |                   | Supplier         | : |        |
| Order By     | : | johari            | Type of Claim    | : | TP     |

| S/No | Part Description        | QTY | Cost Price | List Price | Nett Price | S/N       | Disposition Surveyor |
|------|-------------------------|-----|------------|------------|------------|-----------|----------------------|
| 1    | LHF DOOR                | 1   |            | \$ 450.00  |            |           |                      |
| 2    | LHF DOOR RUBBER         | 1   |            | \$ 220.00  |            |           |                      |
| 3    | LHF DOOR GARNISH        | 1   |            | \$ 32.60   |            |           |                      |
| 4    | LH SLIDING DOOR         | 1   |            | \$ 689.90  |            |           |                      |
| 5    | LHR DOOR RUBBER         | 1   |            | \$ 285.00  |            |           |                      |
| 6    | LH SLIDING DOOR GARNISH | 1   |            | \$ 458.00  |            |           |                      |
| 7    | ART WORK                | 1   |            |            |            | \$ 580.00 |                      |
| 8    | COMPANY STICKER         | 1   |            |            |            | \$ 30.00  |                      |
| 9    |                         |     |            |            |            |           |                      |
| 10   |                         |     |            |            |            |           |                      |
| 11   |                         |     |            |            |            |           |                      |
| 12   |                         |     |            |            |            |           |                      |
| 13   |                         |     |            |            |            |           |                      |
| 14   |                         |     |            |            |            |           |                      |
| 15   |                         |     |            |            |            |           |                      |
| 16   |                         |     |            |            |            |           |                      |
| 17   |                         |     |            |            |            |           |                      |
| 18   |                         |     |            |            |            |           |                      |
| 19   |                         |     |            |            |            |           |                      |
| 20   |                         |     |            |            |            |           |                      |
| 21   |                         |     |            |            |            |           |                      |
| 22   |                         |     |            |            |            |           |                      |
| 23   |                         |     |            |            |            |           |                      |
| 24   |                         |     |            |            |            |           |                      |
| 25   |                         |     |            |            |            |           |                      |
| 26   |                         |     |            |            |            |           |                      |
| 27   |                         |     |            |            |            |           |                      |
| 28   |                         |     |            |            |            |           |                      |
| 29   |                         |     |            |            |            |           |                      |
| 30   |                         |     |            |            |            |           |                      |

10:29 AM

Tel: 63837168 / 63837466 Fax: 62815767

Year of Manufacture : **2010**

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*