

Date: 18/01/2023
Vehicle No: SKX4631X
Model: TOYOTA COROLLA ALTIS 1.6L CVT
Chassis: MR053REH104541966-2015
Reg.Year: 2015

Third Party Insurer: ALLIANZ
Third Party Veh No: S1980CD
Date of Accident: 17/01/2023
Estimator: TING AN
Surveyor:

*Not withain
1/1mp &*

Repaired After Paint

5 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP RH	1		<i>By</i> \$850.00
2	FRONT BUMPER	1		<i>mg or</i> \$479.00
3	FRONT BUMPER SIDE BRACKET RH	1		<i>By</i> \$85.00
4	FRONT FENDER RH	1		<i>By</i> \$781.00
5	FRONT FENDER "VVT-I" EMBLEM RH	1		<i>By</i> \$54.00
6	FRONT FENDER INNER SHIELD RH	1		\$200.00
7	FRONT RIM RH	1		\$850.00
8	FRONT DOOR RH	1		<i>By</i> \$1,100.00
9	FRONT DOOR INNER TRIM BOARD RH	1		<i>in</i> \$740.00
10	FRONT DOOR WEATHERSTRIP RH	1		\$145.00
11	FRONT DOOR UPPER HINGE RH	1		<i>By</i> \$95.00
12	FRONT DOOR LOWER HINGE RH	1		<i>By</i> \$95.00
13	FRONT DOOR CHECKER RH	1		\$152.00
14	FRONT DOOR REGULATOR RH	1		\$304.00
15	REAR DOOR RH	1		<i>By</i> \$1,000.00
16	REAR DOOR INNER TRIM BOARD RH	1		<i>in</i> \$680.00
17	REAR DOOR WEATHERSTRIP RH	1		\$145.00
18	REAR FENDER RH	1		REPAIR
19	REAR BUMPER	1		REPAIR
SUB TOTAL				\$7,755.00
LESS 25%				-\$1,938.75
PARTS TOTAL				\$5,816.25

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>By</i> \$50.00
2	FRONT FENDER INNER SHIELD CLIPS RH	1		\$40.00
3	FRONT DOOR INNER TRIM BOARD CLIPS RH	1		<i>By</i> \$50.00
4	REAR DOOR INNER TRIM BOARD CLIPS RH	1		<i>By</i> \$50.00
S/N TOTAL				\$190.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18/01/2023
Vehicle No: SKX4631X
Model: TOYOTA COROLLA ALTIS 1.6L CVT
Chassis: MR053REH104541966-2015
Reg.Year: 2015

Third Party Insurer: ALLIANZ
Third Party Veh No: S1980CD
Date of Accident: 17/01/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

\$1,400.00 *600*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH, REAR FENDER RH, REAR BUMPER & ETC.

\$1,400.00 *1000*

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.

\$150.00 *60*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.

\$120.00 *60*

LABOUR CHARGES TO REMOVE & REPLACE FRONT RIM RH.

\$120.00 *?*

TO WHEEL ALIGNMENT & BALANCING.

\$80.00 *60*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00 *90*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$100.00 *?*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 *20*

LABOUR TOTAL **\$3,610.00**

TING AN**TOTAL****\$9,616.25**

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

