

Date: 18/01/2023

Vehicle No: SKX4631X

Model: TOYOTA COROLLA ALTIS 1.6L CVT

Chassis: MR053REH104541966-2015

Reg.Year: 2015

Third Party Insurer: ALLIANZ

Third Party Veh No: S1980CD

Date of Accident: 17/01/2023

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP RH	1		By \$850.00
2	FRONT BUMPER	1		By \$479.00
3	FRONT BUMPER SIDE BRACKET RH	1		By \$85.00
4	FRONT FENDER RH	1		By \$781.00
5	FRONT FENDER "VVT-I" EMBLEM RH	1		By \$54.00
6	FRONT FENDER INNER SHIELD RH	1		By \$200.00
7	FRONT RIM RH	1		By \$850.00
8	FRONT DOOR RH	1		By \$1,100.00
9	FRONT DOOR INNER TRIM BOARD RH	1		By \$740.00
10	FRONT DOOR WEATHERSTRIP RH	1		By \$145.00
11	FRONT DOOR UPPER HINGE RH	1		By \$95.00
12	FRONT DOOR LOWER HINGE RH	1		By \$95.00
13	FRONT DOOR CHECKER RH	1		By \$152.00
14	FRONT DOOR REGULATOR RH	1		By \$304.00
15	REAR DOOR RH	1		By \$1,000.00
16	REAR DOOR INNER TRIM BOARD RH	1		By \$680.00
17	REAR DOOR WEATHERSTRIP RH	1		By \$145.00
18	REAR FENDER RH	1		REPAIR
19	REAR BUMPER	1		REPAIR
SUB TOTAL				\$7,755.00
LESS 25%				-\$1,938.75
PARTS TOTAL				\$5,816.25

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		By \$50.00
2	FRONT FENDER INNER SHIELD CLIPS RH	1		By \$40.00
3	FRONT DOOR INNER TRIM BOARD CLIPS RH	1		By \$50.00
4	REAR DOOR INNER TRIM BOARD CLIPS RH	1		By \$50.00
S/N TOTAL				\$190.00

Head office

8 Kiang Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 0810 | Fax: (+65) 6481 1693

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 668047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18/01/2023
Vehicle No: SKX4631X
Model: TOYOTA COROLLA ALTIS 1.6L CVT
Chassis: MR053REH104541966-2015
Reg.Year: 2015

Third Party Insurer: ALLIANZ
Third Party Veh No: S1980CD
Date of Accident: 17/01/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

\$1,400.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH, REAR FENDER RH, REAR BUMPER & ETC.

\$1,400.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.

\$150.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.

\$120.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT RIM RH.

nn \$120.00 X

TO WHEEL ALIGNMENT & BALANCING.

\$80.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

nn \$100.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00

LABOUR TOTAL \$3,610.00

TING AN

TOTAL

\$9,616.25

Finalise:

Parts: \$3489.75

Nett: \$150

Labour: \$1890

4/1 : \$5529.75 less 20% = \$4423.80

\$4400

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1312 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A 401-05 Singapore 560047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1031

