

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000634/KWP3Q2**Date:** 27/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00229552100

Claimant Vehicle No : SMA9323A **Insured Vehicle No :** SNC2439Z

Date of Loss: 14/01/2023 Nature of Claim: TP Claim No: SNM23D200484/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA9323A**

Make & Model: TOYOTA HARRIER, 2.0 Premium (A) Engine No: 3ZRB564614

Reg. Date: 30/06/2015 (Man. Year: 2015) Chassis No: ZSU600045797

Colour: Metallic Pearl White Odometer: 91033 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18

Front Left Side: Falken 8 mm Rear Left Side: Falken 8 mm

Front Right Side: Falken 8 mm Rear Right Side: Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,342.30	3,540.36	6,801.94	65.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	990.00	1,220.00	55.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,552.30	4,530.36	8,021.94	63.91
Approved Total (Overridden) (\$\$)		3,600.00		
Nett Amount (\$\$)	12,552.30	3,600.00	8,952.30	71.32

INSPECTION

Date of Assignment: 18/01/2023

Date Inspected: 30/01/2023 Inspected At: Poon Siang Seow (HQ)
160 Sin Ming Drive, #05-13 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2023)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA9323A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	2,378.50 F	*2,021.32 FL
2	1		*TAIL GATE BADGE HARRIER	Necessary	75.50 F	*75.50 FL
3	1		*TAIL GATE DAMPER (\$1200.00) (50%)	Punctured	2,565.80 FS	*600.00 FS
4	2		*TAIL GATE DAMPER CABLE	Serviceable	1,350.95 F	*- FL
5	1		*TAIL GATE LOCK	Repair	455.90 F	*- FL
6	1		*TAIL GATE W/S MOULDING	Necessary	148.90 F	*148.90 FL
7	1		*REAR PANEL	Repair	855.90 F	*- FL
8	1		*REAR BUMPER	Buckled / Dented	1,395.95 F	*985.20 FL
9	1		*REAR BUMPER SENSOR	Scratched	350.00 FS	*200.00 FS
10	2		*REAR BUMPER RETAINER	Serviceable	342.00 F	*- FL
11	1		*REAR BUMPER LOWER COVER	Buckled	422.90 F	*422.90 FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	10,342.30 4,453.82
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 913.46
					Total Parts (\$\$)	10,342.30 3,540.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING	New	100.00	30.00
2	TO REMOVE AND REFIT REAR W/S	New	250.00	120.00
3	PANEL BEATING	New	980.00	400.00
4	SPRAY PAINTING	New	880.00	440.00
Gross Labour Cost (\$\$)			2,210.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >