

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 08 May 2023

**Preliminary Advice**

Vehicle No	: GBK606X	Accident Date	: 14/01/2023
Make	: TOYOTA HIACE	Policy No.	: SP2004006721
Assignment Date	: 18/01/2023	Excess	: S\$1,500.00
Date of Inspection	: 19/01/2023	Est. Duration of Repair	: 7
Inspection At	: FULCO AUTOCARE PTE LTD (HQ) 176 SIN MING DRIVE #03-02 SIN MING AUTOCARE SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,549.45	(Estimate \$25,979.40 + Supplementary \$4,570.05)
Revised Amount	:S\$	15,165.81	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	15,165.81	
Lump Sum Repair	:S\$	11,900.00	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	16,864.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,136.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : KINDLY APPROVE ON SUPPLEMENTARY & SOME CHECK ITEMS.